SCREENING SITE INSPECTION REPORT FOR

CONTAINER CORPORATION
WABASH, INDIANA
U.S. EPA ID: INDO05432653

SS ID: NONE TDD: F05-8710-070 PAN: FIN0656SB



978245

JULY 13, 1990



ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415 International Specialists in the Environment

SIGNATURE PAGE
FOR
SCREENING SITE INSPECTION REPORT
FOR
CONTAINER CORPORATION
WABASH, INDIANA

SS ID: NONE TDD: F05-8710-070 PAN: FIN0656SB

U.S. EPA ID: IND005432653

Prepared	by:		Date:	7/20/90
		Angelo Carpodinis		,
		FIT Team Leader		
		Ecology and Environment, Inc.		
Reviewed	by:	Jung furh	Date:	7/20/90
		Larry Łweck		/ 1
		FIT Unit Manager		
		Ecology and Environment, Inc.		
Approved	by 🗸	Jume (Moall	Date:	7/20/80
	\sim	Jerome D. Oskvarek		
	- 1	FIT Office Manager		
	レ	Ecology and Environment, Inc.		

TABLE OF CONTENTS

Section			Page
1	INTR	ODUCTION	1-1
2	SITE	BACKGROUND	2-1
	2.1	INTRODUCTION	2-1
	2.2	SITE DESCRIPTION	2-1
	2.3	SITE HISTORY	2-1
3	SCREI	ENING SITE INSPECTION PROCEDURES AND FIELD	
	OBSEI	RVATIONS	3-1
	3.1	INTRODUCTION	3–1
	3.2	SITE REPRESENTATIVE INTERVIEW	3-1
	3.3	RECONNAISSANCE INSPECTION	3-1
	3.4	SAMPLING PROCEDURES	3-4
4	ANAL	YTICAL RESULTS	4-1
	4.1	INTRODUCTION	4-1
	4.2	RESULTS OF CHEMICAL ANALYSIS OF FIT-	
		COLLECTED SAMPLES	4-1
5	DISC	USSION OF MIGRATION PATHWAYS	5-1
	5.1	INTRODUCTION	5-1
	5.2	GROUNDWATER	5–1
	5.3	SURFACE WATER	5-3
	5.4	AIR	5–3
	5.5	FIRE AND EXPLOSION	5-4
	5.6	DIRECT CONTACT	5-4
6	REFE	RENCES	6-1

Table of Contents (Cont.)

Appendix		Page
A	SITE 4-MILE RADIUS MAP	A-1
В	U.S. EPA FORM 2070-13	B-1
С	FIT SITE PHOTOGRAPHS	C-1
D	U.S. EPA TARGET COMPOUND LIST AND TARGET ANALYTE LIST QUANTITATION/DETECTION LIMITS	D-1
E	WELL LOGS OF THE AREA OF THE SITE	E-1

LIST OF FIGURES

Figure		<u>Page</u>
2-1	Site Location	2-2
3-1	Site Features	3-3
3-2	Soil/Sediment Sampling Locations	3-5

LIST OF TABLES

<u>Table</u>		Page
4-1	Results of Chemical Analysis of FIT-Collected Soil/	
	Sediment Samples	4-2

1. INTRODUCTION

Ecology and Environment, Inc. (E & E), Field Investigation Team (FIT) was tasked by the United States Environmental Protection Agency (U.S. EPA) to conduct a screening site inspection (SSI) of the Container Corporation site under contract number 68-01-7347.

The site was initially discovered in 1979 by David Brown and Jim Kelly of the Indiana State Board of Health (ISBH). The site was discovered when the ISBH Division of Sanitary Engineering, Solid Waste Management Section, investigated a citizen complaint from Tony Parett alleging that potentially hazardous sludge was being dumped by Container Corporation of America (the company will hereinafter be referred to as CCA) behind his residence in Wabash, Indiana (Brown 1979).

The site was evaluated in the form of a preliminary assessment (PA) that was submitted to U.S. EPA. The PA was prepared by Mary Anne Hunter of the Indiana Department of Environmental Management (IDEM) and is dated July 24, 1987. PA preparation, as well as other pre-remedial functions performed by state agencies in Indiana, are now handled by IDEM.

FIT prepared an SSI work plan for the Container Corporation site under technical directive document (TDD) F05-8710-070, issued on October 15, 1987. The SSI work plan was approved by U.S. EPA on July 8, 1989. The SSI of the Container Corporation site was conducted on September 27, 1989, under amended TDD F05-8710-070, issued on August 25, 1989.

The FIT SSI included an interview with site representatives, a reconnaissance inspection of the site, and the collection of six soil samples and three sediment samples.

The purposes of an SSI have been stated by U.S. EPA in a directive outlining Pre-Remedial Program strategies. The directive states:

All sites will receive a screening SI to 1) collect additional data beyond the PA to enable a more refined preliminary HRS [Hazard Ranking System] score, 2) establish priorities among sites most likely to qualify for the NPL [National Priorities List], and 3) identify the most critical data requirements for the listing SI step. A screening SI will not have rigorous data quality objectives (DQOs). Based on the refined preliminary HRS score and other technical judgement factors, the site will then either be designated as NFRAP [no further remedial action planned], or carried forward as an NPL listing candidate. A listing SI will not automatically be done on these sites, however. First, they will go through a management evaluation to determine whether they can be addressed by another authority such as RCRA [Resource Conservation and Recovery Act].... Sites that are designated NFRAP or deferred to other statutes are not candidates for a listing SI.

The listing SI will address all the data requirements of the revised HRS using field screening and NPL level DQOs. It may also provide needed data in a format to support remedial investigation work plan development. Only sites that appear to score high enough for listing and that have not been deferred to another authority will receive a listing SI. (U.S. EPA 1988)

U.S. EPA Region V has also instructed FIT to identify sites during the SSI that may require removal action to remediate an immediate human health or environmental threat.

2. SITE BACKGROUND

2.1 INTRODUCTION

This section presents information obtained from SSI work plan preparation, the site representative interview, and a reconnaissance inspection of the site.


2.2 SITE DESCRIPTION

The Container Corporation site is an approximately 20-acre parcel of land containing an active paper mill. Two water treatment plants and the main plant building, which includes several processing units, occupy approximately 1/3 of the site. Paper waste is disposed of on-site at different locations. The site is located on West Factory Street, in downtown Wabash, Noble Township, Wabash County, Indiana (T.27N., R.6E.) (see Figure 2-1 for site location). The Wabash River runs approximately 20 feet south of the site boundary. A 4-mile radius map of the Container Corporation site is provided in Appendix A.

2.3 SITE HISTORY

CCA, the current site owner, acquired the site in approximately 1933. Smurfit Corporation became CCA's parent company in 1986. Dymon Match Corporation owned the property from 1890 to 1933. Dymon Match Corporation operated a plant for the production of wooden matches on-site (Smith 1989).

CCA is a manufacturer of rolled or stacked bulk paper, in varying grades. The facility receives and reprocesses spent paper products.



SOURCE: Ecology and Environment, Inc. 1990; BASE MAP: USGS, Wabash, IN Quadrangle, 7.5 Minute Series, 1963.




FIGURE 2-1 SITE LOCATION

Solid waste from the process is sent to landfills; waste sludge is sent to farms (Smith 1989).

The Container Corporation site also discharges process water to the Wabash River. CCA holds a National Pollutant Discharge Elimination System (NPDES) permit for the discharge. The permit number is unknown. There are two lagoons, which are not currently active, that were in operation for approximately 30 years. The lagoons were unlined (Smith 1989).

No remedial-response or regulatory actions regarding this site are on file or documented with appropriate state or federal agencies. CCA had not made the feedstock, waste type, or composition information available at the time this report was written. Two requests for the information were made by E & E. Asbestos removal was in progress at the site during SSI (Townley 1989).

3. SCREENING SITE INSPECTION PROCEDURES AND FIELD OBSERVATIONS

3.1 INTRODUCTION

This section outlines procedures and observations of the SSI of the Container Corporation site. Individual subsections address the site representative interview, reconnaissance inspection, and sampling procedures. Rationales for specific FIT activities are also provided. The SSI was conducted in accordance with the U.S. EPA-approved work plan.

The U.S. EPA Potential Hazardous Waste Site Inspection Report (Form 2070-13) for the Container Corporation site is provided in Appendix B.

3.2 SITE REPRESENTATIVE INTERVIEW

Angelo Carpodinis, FIT team leader, conducted an interview with three CCA representatives: Bruce Smith, Plant Engineer; Richard Townley, Project Engineer; and Donald A. Hughes, Boxboard Group Technical Director. The interview was conducted on September 27, 1989, at approximately 9:00 a.m. at Smith's office. Alan K. Baumann, Environmental Engineer, of U.S. EPA (Region V), and Clifford Florczak, of FIT, were also present at the interview. The interview was conducted to gather information that would aid FIT in conducting SSI activities.

3.3 RECONNAISSANCE INSPECTION

Following the site representative interview, FIT conducted a reconnaissance inspection of the Container Corporation site and surrounding area in accordance with E & E health and safety guidelines. The reconnaissance inspection was begun on September 27, 1989, at approximately 10:30 a.m. and included a walk-through of the site to determine

appropriate health and safety requirements for conducting on-site activities and to make observations to aid in characterizing the site. FIT also determined sampling locations during the reconnaissance in-spection. FIT was accompanied by Townley of CCA and Baumann of U.S. EPA during the reconnaissance inspection.

Reconnaissance Inspection Observations. The Container Corporation site is located in a flat area at an approximate elevation of 660 feet above sea level. Land use in the vicinity of the site is primarily residential, with some industrial and agricultural land use as well.

The site is bordered by a residential area to the north, the Wabash River to the south, a cornfield and an industrial building to the west, and residences and the city wastewater treatment plant to the east.

The site is approximately 90% fenced (see Figure 3-1 for locations of site features). Security guards are present at the site only after working hours. No other means of security is used at the site. Gates are located in the fence along the site's northern and southeastern boundaries.

The site contains two lagoons located in the western portion of the site. The lagoons, not currently in use, had been used for approximately 30 years for paper recycling/production. The lagoons, which are approximately 8 feet deep and have no liners, were cleaned and will not be used again (Townley 1989). FIT observed paper waste in both lagoons and small areas of liquid accumulation in the north lagoon.

The main plant building is located along the northern boundary of the site. The facility's primary water treatment plant is located between the main building and the lagoons to the west. An overflow of muddy wastewater was observed on the northeast side of the primary treatment plant. There is a secondary water treatment plant in the southeast corner of the site. A sharp odor of hydrogen sulfide emanated from the secondary treatment plant (Townley 1989).

There were several disposal areas located around the site. An excavated trench holding general refuse was located in the woods south of the lagoons. There was a pile of buried paper waste in a vegetated area southeast of the trench. West of the secondary water treatment plant was another former paper waste disposal area. During the SSI, FIT observed paper sludge being disposed of in an area 100 feet north of the




FIGURE 3-1 SITE FEATURES

secondary treatment plant. The sludge was to be removed by disposal trucks (Townley 1989).

A pile of uncovered paper packages was observed in the center of the site. Paper from the pile was blowing all over the site. A pile of abandoned equipment was located in the upper northwest corner of the site. An old dry outfall was observed off-site approximately 5 feet north of the Wabash River.

Coal, used to fire boilers on-site, was observed on the ground near the northeast corner of the site. Several open drums of waste were observed approximately 100 feet north of the lagoons. The drums contained hazardous waste, and they were to be removed (Townley 1989). More drums were observed near the northwest side of the main building. None of the these drums contained waste (Townley 1989).

Nine production wells exist on-site (Smith 1989). Four of these wells were observed by FIT and are currently in service. Beer cans were observed by FIT along the north bank of the Wabash River. FIT did not observe any leachate collection system or surface water diversion structures at the site. Photographs of the Container Corporation site are included in Appendix C.

3.4 SAMPLING PROCEDURES

Samples were collected by FIT at locations selected during the reconnaissance inspection to determine whether U.S. EPA Target Compound List (TCL) compounds or Target Analyte List (TAL) analytes were present at the site. The TCL and TAL are included with corresponding quantitation/detection limits in Appendix D.

On September 27, 1989, FIT collected nine soil/sediment samples, two of which were potential background samples. Townley and Hughes of CCA and Baumann of U.S. EPA accompanied FIT during part of the soil/sediment sampling activities. FIT offered portions of the soil/sediment samples collected to Smith, who declined the offer.

Soil/Sediment Sampling Procedures. Subsurface soil sample S2 was collected approximately 100 feet north of the secondary water treatment plant, where the sludge waste from the water plant was being dumped, to determine whether TCL compounds or TAL analytes were present or had migrated from the dump area (see Figure 3-2 for soil/sediment sampling




FIGURE 3-2 SOIL/SEDIMENT SAMPLING LOCATIONS

locations). Subsurface soil sample S3 was collected inside an excavated pit to determine whether TCL compounds or TAL analytes were present in the pit. Surface soil samples S4 and S5 were collected from the lagoons to determine whether TCL compounds or TAL analytes were present. Surface soil sample S6 was collected at an old disposal site to determine whether TCL compounds or TAL analytes were present.

A potential background soil sample, S1, was collected in what appeared to be an undisturbed vegetated area in the middle portion of the site. The background sample was collected to determine the representative chemical content of the soil in the area of the site.

Sediment sample S8 was collected where the outfall discharges to the Wabash River to determine whether TCL compounds or TAL analytes were migrating from the site to the river. Sediment sample S9 was collected from the Wabash River near the downstream end of the site to determine whether TCL compounds or TAL analytes were migrating downstream. Sediment sample S7 was collected in the Wabash River upstream from the site, as a potential background sample. The downstream sediment sample, S9, was collected first to prevent contamination of other sediment samples. Sample S7 was collected last.

Samples S2 and S3 were collected using a hand auger. The hand auger was used to gather soil at a depth of approximately 3 feet. Samples S1, S4, S5, S6, S7, S8, and S9 were collected using a trowel. The trowel was used to gather soil/sediment at a depth of approximately 6 inches. Each soil/sediment sample was placed in a stainless steel bowl. The sample material was then transferred from the bowl to sample bottles, using a stainless steel spoon (E & E 1987). For all soil/sediment samples, volatile organic bottles were filled first (E & E 1987).

Production wells were discovered on-site by FIT during the SSI. Because the work plan for the SSI did not include sampling of wells, the four production wells currently in service at the site were not sampled.

Standard E & E decontamination procedures were adhered to during the collection of all soil/sediment samples. The procedures included the scrubbing of all equipment (e.g., trowel, hand auger, bowls, and spoons) with a solution of detergent (Alconox) and distilled water, and triple-rinsing the equipment with distilled water before the collection of each sample (E & E 1987). All soil/sediment samples were packaged and shipped in accordance with U.S. EPA-required procedures.

As directed by U.S. EPA, all soil/sediment samples were analyzed using the U.S. EPA Contract Laboratory Program (CLP) for TCL compounds by EMS Laboratories of Indianapolis, Indiana, and EMS Laboratories of Lakewood, New Jersey, and for TAL analytes by Associated Laboratories, Inc., of Orange, California.

4. ANALYTICAL RESULTS

4.1 INTRODUCTION

This section presents results of the chemical analysis of FIT-collected soil/sediment samples for TCL compounds and TAL analytes.

4.2 RESULTS OF CHEMICAL ANALYSIS OF FIT-COLLECTED SAMPLES

<u>Soil/Sediment Samples</u>. Chemical analysis of FIT-collected soil/ sediment samples revealed substances from the following groups of TCL compounds and TAL analytes: halogenated hydrocarbons, polyaromatic hydrocarbons (PAHs), pesticides, polychlorinated biphenyls (PCBs), heavy metals, metals, and soil/sediment constituents common to the area of the site; cyanide was also detected (see Table 4-1 for complete chemical analysis results of FIT-collected soil/sediment samples).

Quantitation/detection limits used in the analysis of soil/sediment samples are provided in Appendix D.

The analytical data for the chemical analysis of soil/sediment samples collected for this SSI have been reviewed by U.S. EPA and FIT for compliance with terms of the FIT contract, and the review has been approved by U.S. EPA. Any additions, deletions, or changes to the data have been incorporated in the chemical analysis results tables presented in this section.

Table 4-1 RESULTS OF CHEMICAL ANALYSIS OF FIT-COLLECTED SOIL/SEDIMENT SAMPLES

Cample Collection Information	01	00		24	Sample Number	0.5			
and Parameters	Sl	S2	53	S4	\$5	S6	S7	S8	59
Jate	9/27/89	9/27/89	9/27/89	9/27/89	9/27/ 89	9/27/89	9/27/89	9/27/89	9/27/89
Time	1240	1200	1225	1150	1155	1200	1300	1305	1205
TLP Organic Traffic Report Number	EGR39	EGR40	EGR41	EGR42	EGR43	EGR44	EGR45	EGR46	EGR47
CLP Inorganic Traffic Report Number	MEEQ78	NEFQ79	MEFQ80	MEEO81	MEFQ92	MEFQ83	MEFQ84	MEFQ85	MEE086
Second Bakasaka I					į				
Compound Detected (values in µg/kg)									
7.43.062 10 h4.64.									
Volatile Organics									
hloroform	4J	8	4 J	4 J	10	14		6	6J
Semivolatile_Organics									
fluoranthene					- }			200J	
Pesticides/PCBs									
Heptachlor	13J	10J			-		13J		
Aroclor 1254		880			†				820
Analyte Detected									
(values in mg/kg)									
luminum	9,840JE	16,100JE	8,680JE	16,900JE	15,30 JE	14,500JE	6,910JE	4,950JE	5,010JE
entimony	17.3JN	12.3JNB	14.3JN	11.5JNB	17.kJN	11.4JNB	12.6JNB	11.5JNB	12.6JNB
arsenic	4.3	6.6	3.3	4.6	4.1	5 . 7	3.6	3.1	2.9
parium	65.9JN	114JN	58.5JN	156JN	92 . ₺JN	113JN	43.3JNB	35.5JNB	28.8JNB
peryllium		1.6		1.5	1.3	1.3			
cadmium	1.1	1.8			1.1	1.0B			
alcium	36,300JE	20,700JE	18,300JE	16,000JE	21,3 0 JE	12,1 0 0JE	16,100JE	30,600JE	23,700JE
hromium	16.4	71.4	15.2	24.7	22 🎝	22.1	10.5	8.6	8.2
obalt	8.3B	12.4B	7.9B	11.3B	12.	12.2B	6.2B	6.6B	4.7B
copper	20.3	50,4	16.3	22.3	19∄	25.3	9.33	10.5J	8.OJ
ron	17,300JE	24,300JE	13,200JE	22,600JE	23,2 0 JE	25,300JE	10,800JE	8,990JE	8,670JE
ead	26.4	211	10.7	10.8	8	11.1	7.6	9.3	10.2
ragnesium	16,800JE	9,930JE	10,700JE	11,600JE	13,8 0 je	7,370JE	9,440JE	10.800JE	10,000JE
nanganese	543JNE	569JNE	223JNE	421JNE	497 NE	1,220JNE	325JNE	292JNE	253JNE
n é r (106y	0.10J	täR	0.11.	0.123	4	0.121			0.11J
nickel	21-9	28.7	14.7	28.7	28 🏚	29.1	13.6	13.5	10.6
otassium	1,910	2,610	1.320	3,080	2.7 Ġ	2.160	1.290	909B	933B
elenium		0.508			.				
ilver	5.23	5.93	<u>4.4</u> 7	5.83	5 . 1	5.53	5.03	4.63	4.73
edium	93,53B	120JB	86.438	132JF	5 . 1 1 7 38	132JB	97.7JB	96JP	99.21
hallıum	0.50B			0.848	4	0.248		0.29B	0.258
vanadium	19.3	27.5	16.8	33.7	29 🛊	26.7	15.3	10.98	11.88
zina	76.7JNE	263JNE	88.4JNE	96.9JNE	81. \$ ne	104JNE	40.6JNE	42.8JNE	33JNE
cyanide				0.91					

⁻⁻ Not detected.

•

Table 4-1 (Cont.)

COMPOUND QUALIFIER	DEFINITION
J	Indicates an estimated value.
ANALYTE QUALIFIERS	DEF INITION
E	Estimated or not reported due to interference. See laboratory narrative.
И	Spike recoveries outside QC protocols, which indicates a possible matrix problem. Data may be biased high or low. See spike results and laboratory narrative.
8	Value is real, but is above instrument DL and below CRDL.
J	Value is above CRDL and is an estimated value because of a QC protocol.
R	Results are unusable due to a major violation of QC protocols.
Source: Ecology and Environment, Inc. 1990.	

INTERPRETATION

Compound value may be semiquantitative.

INTERPRETATION

Analyte or element was not detected, or value may be semiquantitative.

Value may be quantitative or semiquantitative.

Value may be quantitative or semiquantitative.

Value may be semiquantitative.

Analyte value is not usable.

5. DISCUSSION OF MIGRATION PATHWAYS

5.1 INTRODUCTION

This section presents discussions of data and information pertaining to potential migration pathways and targets of TCL compounds and TAL analytes that are possibly attributable to the Container Corporation site.

The five migration pathways of concern discussed are groundwater, surface water, air, fire and explosion, and direct contact.

5.2 GROUNDWATER

Groundwater samples were not collected during the SSI of the Container Corporation site. However, a potential exists for TCL compounds and TAL analytes to migrate from the site to groundwater in the vicinity of the site, based on the following information.

- TCL compounds and TAL analytes including fluoranthene (200J µg/kg), Aroclor 1254 (880 µg/kg), and lead (211 mg/kg), were detected in on-site soil/sediment samples from the Wabash River at concentrations greater than those detected in the background soil/sediment samples (see Table 4-1 for definitions and interpretations of qualifiers).
- The site does not have any liners underlying the disposal areas or a leachate collection system (Smith 1989).

• No evidence of a continuous, naturally occurring confining layer exists at the site (Thomson 1990).

The potential for TCL compounds and TAL analytes to migrate to groundwater in the vicinity of the site is also based on the following geological information.

The uppermost geologic unit in the site area is composed of undifferentiated tills consisting of a mixture of sands, gravels, and clays of moderate permeability. According to area well logs (see Appendix E), the depth of the surficial material ranges from 60 to 100 feet. Limestone bedrock of the early and middle Silurian period underlies the surficial material (Thomson 1990).

The major aquifers are sand and gravel deposits, at depths of approximately 30 feet, and an underground river valley in the limestone bedrock at a depth of approximately 190 feet (Hiner 1990). The Indiana Cities Water Department municipal wells and the great majority of residential wells Non-responsive, well locations use the limestone river valley aquifer as a source of drinking water (Thomson 1990). The sand and gravel aquifers are hydraulically connected with the deeper limestone aquifer (Thomson 1990). These aquifers together constitute the aquifer of concern. Water from the municipal wells is blended before distribution (Hiner 1990). The closest municipal well is located 1 1/2 miles southeast from the site.

Nine production wells exist on-site. Four of these wells are active. The sand and gravel aquifers are the source of water for the production wells, from a depth of approximately 30 feet (Smith 1989).

The potential targets of groundwater contamination include the approximately 15,800 persons who are served by wells drawing from the aquifer of concern within a 3-mile radius of the site. This target population was calculated by counting houses on United States Geological Survey (USGS) topographic maps of the area (USGS 1963, 1969). The counted houses (309) were then multiplied by the persons-per-household average of 2.76 for Wabash County (U.S. Bureau of the Census 1982). The resulting population figure was added to the approximately 15,000 persons served by the Indiana Cities Water Department municipal wells.

5.3 SURFACE WATER

The Wabash River flows from east to west along the southern edge of the site. A potential exists for contaminants from the site to reach the Wabash River via general surface water runoff pathways, based on the following information.

- TCL compounds and TAL analytes were detected in soil/ sediment samples collected at the site and along the Wabash River at levels above those detected in background samples.
- No surface water diversion structures were present at the site.
- The Wabash River is located downgrade (approximately 5%) from the site.
- An outfall located a few feet from the river may increase the potential for contaminants to reach surface water. Although the pipe appeared to be dry at the time of the SSI, laboratory analysis of sample S8, collected where the outlet discharges into the river, revealed the presence of TCL compounds, as did downstream sediment sample S9.

The population potentially affected by TCL compounds migrating off-site includes persons who use surface water in the vicinity of the site for fishing and recreational purposes. No drinking water intakes are known to exist in surface water bodies within 15 miles downstream of the site.

5.4 AIR

A release of TCL compounds or TAL analytes to the air was not documented during the SSI of the Container Corporation site. During the reconnaissance inspection, FIT site-entry instruments (OVA 128, explosimeter, oxygen meter, hydrogen cyanide tubes, and radiation monitor) did not detect levels above background concentrations at the site. In

accordance with the U.S. EPA-approved work plan, further air monitoring was not conducted by FIT.

A potential does exist for TCL compounds and TAL analytes to migrate from the site via windblown particulates. This potential is based on the following information.

- TCL compounds and TAL analytes were detected in on-site soil samples at concentrations greater than concentrations detected in the background soil sample.
- Certain disposal areas on-site were not covered by vegetation.

The air target population within a 4-mile radius of the site includes approximately 16,612 persons. This target population was calculated in the manner described in Subsection 5.2.

5.5 FIRE AND EXPLOSION

According to federal, state, and local file information reviewed by FIT, and an interview with the fire chief of Wabash, Indiana (McMullet 1989), no documentation exists of an incident of fire or explosion at the site. According to FIT observations and site-entry equipment readings, no potential for fire or explosion existed at the site at the time of the SSI.

5.6 DIRECT CONTACT

According to federal, state, and local file information reviewed by FIT, observations made during the SSI, and the interview with site representatives, no incidents of direct contact with TCL compounds or TAL analytes at the Container Corporation site have been documented.

There is a potential for the public to come into direct contact with TCL compounds and TAL analytes at the site, based on the following information.

- TCL compounds and TAL analytes were detected in on-site surface soil samples at concentrations greater than concentrations detected in the background sample.
- The site is not completely fenced, and no security guards or other means of security are used to restrict access to the site during daylight hours.

The target population within a 1-mile radius of the site is approximately 6,000 persons. This target population was calculated in the manner described in Subsection 5.2, with the exception that a planimeter was used to calculate the portion of the population that falls within municipal boundaries inside the 1-mile radius of the site.

6. REFERENCES

- Brown, David, May 1, 1979, Sanitary Engineer, ISBH, Division of Sanitary Engineering, Solid Waste Management Section, refuse facility inspection report.
- E & E, 1987, Quality Assurance Project Plan Region V FIT Conducted Site Inspections, Chicago, Illinois.
- Hiner, Boyd, January 23, 1990, District Supervisor, Indiana Cities Water Department, telephone conversation, contacted by Angelo Carpodinis of E & E.
- McMullet, Mike, July 18, 1989, Fire Chief, Wabash Fire Department, Wabash, Indiana, telephone conversation, contacted by Tim Danzer of E & E.
- Smith, Bruce, September 27, 1989, Plant Engineer, CCA, site representative interview, conducted by Angelo Carpodinis of E & E.
- Thomson, Todd, January 30, 1990, Industrial Minerals Specialist, Indiana Geological Survey, telephone conversation, contacted by Angelo Carpodinis of E & E.
- Townley, Richard, September 7, 1989, Project Engineer, CCA, site representative interview, conducted by Angelo Carpodinis of E & E.

- U.S. Bureau of the Census, 1982, 1980 Census of Population, Characteristics of the Population, General Population Characteristics,
 Indiana, Washington, D.C.
- U.S. EPA, February 12, 1988, Office of Solid Waste and Emergency Response, Pre-Remedial Strategy for Implementing SARA, Directive number 9345.2-01, Washington, D.C.
- USGS, 1963, Rich Valley, photorevised 1981; 1963 Wabash, photorevised 1981; 1969, Somerset, Indiana Quadrangles, 7.5 Minute Series: 1:24,000.

4635:8

APPENDIX A

SITE 4-MILE RADIUS MAP

SDMS US EPA Region V

Imagery Insert Form

Document ID:

			1
294587			
			ı

Some images in this document may be illegible or unavailable in SDMS. Please see reason(s) indicated below:

	Illegible due to bad source documents. Image(s) in SDMS is equivalent to hard copy.
	Specify Type of Document(s) / Comments:
	Includes COLOR or RESOLUTION variations. Unless otherwise noted, these pages are available in monochrome. The source document page(s) is more legible than the images. The original document is available for viewing at the Superfund Records Center.
	Specify Type of Document(s) / Comments:
	Confidential Business Information (CBI). This document contains highly sensitive information. Due to confidentiality, materials with such information are not available in SDMS. You may contact the EPA Superfund Records Manager if you wish to view this document. Specify Type of Document(s) / Comments:
X	Unscannable Material: Oversized X or Format. Due to certain scanning equipment capability limitations, the document page(s) is not available in SDMS. The original document is available for viewing at the Superfund Records center.
	Specify Type of Document(s) / Comments:
	APPENDIX A: SITE 4-MILE RADIUS MAP
	Document is available at the EPA Region 5 Records Center. Specify Type of Document(s) / Comments:
	Specify Appe of Documents,
	II I

APPENDIX B

U.S. EPA FORM 2070-13

POTENTIAL HAZARDOUS WASTE SITE

	I. IDENTIFICATION						
	01 STATE	02 SITE NUMBER					
Į	IIN !	Dans 432653					

SEPA	SITE INSPECTION REPORT PART 1 - SITE LOCATION AND INSPECTION INFORMATION OF STATE LOCATION AND INSPECTION INFORMATION					
II. SITE NAME AND LOCAT	ION					
O1 SITE NAME (Legal, common, or de			02 STREET, ROUTE NO., O	R SPECIFIC LOCATION IDENTIFIER		
Container C	andar time		455 W.	Factory Street		
Container G	7 1010109		04 STATE 05 ZIP CODE	06 COUNTY	07COUNTY 08 C DNG	
Wabash	·		IN 46998	Wabash	169 C5	
OP COCFIDINATES LATITUDE 4'0 47'32'.N	0.85 49 55".W	10 TYPE OF OWNERSH A. PRIVATE D. F. OTHER -		C C. STATE D D. COUNTY		
III. INSPECTION INFORMA						
01 DATE OF INSPECTION	02 SITE STATUS	03 YEARS OF OPERAT				
9,27,89	D ACTIVE		1933 Prese			
MONTH DAY YEAR 04 AGENCY PERFORMING INSPE] BEG	NNING YEAR ENDING Y	/EAR		
	<i>1- i 1</i>	Environment	□ C. MUNICIPAL □ (D. MUNICIPAL CONTRACTOR		
DE STATE DE STATEC	- 1 ' (A	lame of firm)	G. OTHER	<u> </u>	(Name of fam)	
	(*	ierne of firm)	E G. OINCI	(Specify)	· · · · · · · · · · · · · · · · · · ·	
05 CHIEF INSPECTOR		06 TITLE	1 /-	07 ORGANIZATION Ecology uncl	08 TELEPHONE NO.	
Augelo Carpodi	1415	Chemi	cal tugineer	Cyrivoyment Inc	131816638415	
09 OTHER INSPECTORS		10 TITLE	7	11 ORGANIZATION	12 TELEPHONE NO.	
Cliff Flores	ak i	1 Ch	emist	Ele Inc	131216639415	
Ting Days	•		,	Ede, Inc	31216639415	
			mapher		13/21 6639145	
Mark Satter	berg:	Bic	ologist	Eft, Inc		
Larry Lue	ck	Geo	logist	Eft, Inc	13121 66394/15	
Jaqueline Lu	nubery	Geo	chemist	CFE, Inc	131216639415	
13 SITE REPRESENTATIVES INTE	RVIEWED 0	14 TITLE	15ADDRESS	DVICION	16 TELEPHONE NO	
Bruce Su	cith	Pluy & Engli		1000	· (219)563-3.02	
Donald A.	Hughes	Buxbuard Oil	coop Boxboard	Mill Division les y street 45048-2107	15131 484-484E	
Richard To	ruyley		ineer wabash		(219) 5633108	
	7				()	
					() -	
		*		_	()	
	:					
	18 TIME OF INSPECTION	19 WEATHER COND				
(Check one) IF PERMISSION [] WARRANT	900 AM	50	uny, 65%			
IV. INFORMATION AVAIL	ABLE FROM				· · · · · · · · · · · · · · · · · · ·	
TOATVIXX) 10		02 OF (Agency/Organ	tration)		03 TELEPHONE NO.	
Harry At			SHWM		1471838-8927	
04 PERSON RESPONSIBLE FOR	SITE INSPECTION FORM	05 AGENCY	06 ORGANIZATION	07 TELEPHONE NO.	OB DATE	
Augelo Carpo	diurs	EPA	Eurivorment	(312)668 9415	MONTH SIAY YEAR	

•		DΛ
	-	PA
- TO -	_	

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 2 - WASTE INFORMATION

I. IDENTIFICATION					
OI STATE	02 SITE NUMBER 0 02 5 438653				
LLN	10 05 952625				

WEI	A		PART 2 - WAST	E INFORMATIO		IN Da	<u> 5432653 </u>
II. WASTES	TATES, QUANTITIES, AN	D CHARACTERI	STICS				
O1 PHYSACAL STATES (Check af Inal Apply) ID A SOLID ID B POWDER, FINES ID G SLUDGE ID OTHER O2 WASTE QUANT (Meanures of musical m		That site Versie quantities Maching and Descriptions D		POSIVE DE INFECTIOUS DE EXPLOSIVE OACTIVE DE FLAMMABLE DE REACTIVE			
III. WASTE T	(Specify)	NO OF DRUMS _		<u> </u>	· · · · · · · · · · · · · · · · · · ·		
CATEGORY	SUBSTANCE N	AME	01 GROSS AMOUNT	2 UNIT OF MEASUR	E 03 COMMENTS		
SLU	SLUDGE				Informa.	ling was i	10 t
OLW.	OILY WASTE				made avai	. 11 1	
SOL	SOLVENTS		Vykyowy	47/69	Represento		
CES	PESTICIDES		Unkung	12/kg	14 torus t	low is down	FIT
000	OTHER ORGANIC CH	HEMICALS	Uu/ Khown	45/ks	Sampling	12 1100	
IOC	INORGANIC CHEMIC	ALS			7 7 7		
ACD	ACIDS						
BAS	BASES						
MES	HEAVY METALS		Dyknown	17/Kg	1		
IV. HAZARD	OUS SUBSTANCES (See A)	opendix for most frequent	7				77
O1 CAREGORY	02 SUPSTANCE N	AME	03 CAS NUMBER	04 STORAGE DI	SPOSAL METHOD	05 CONCENTRATION	CENCENTRATION
	see	Section	4				
	for	a Co	inflete				
	list of	Compounds	and				
	analy tes	detect	d 14 Sam	ples			
	Cullec fed	by	FIT				
V. FEEDST	OCKS (See Appendix for CAS Numb	ens)					
CATEGOR	Y 01 FEEDSTOC	CK NAME	02 CAS NUMBER	CATEGORY	D1 FEEDST	OCK NAME	DE CAS NUMBER
FDS				FDS			
FDS	Vuknow.	1		FDS			
FDS				FDS			
FD\$			<u> </u>	FDS			
	ES OF INFORMATION (Cre						
50	tate and F. I conducted	IT file	c 11.	tion, Cl	190-	I. llinois	
55	'I conducted	04 .	Je ptem be	21,	175 9		

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

	I. IDENTIFICATION				
-	01	STATE	02 STE MAIBER 0005 43 26:3		
l	Ĺ	Ν	0005432653		

E MAZARDOUS CONDITIONS AND INCIDENTS	
DI III A. GROUNDWATER CONTAMINATION 15800	02 D OBSERVED (DATE:) POTENTIAL C ALLEGED 04 NARRATIVE DESCRIPTION
see section 52	for groundwater intormation
B SURFACE WATER CONTAMINATION GREEN POPULATION POTENTIALLY AFFECTED:	02 TO OBSERVED (DATE:) POTENTIAL C ALLEGED 04 NARRATIVE DESCRIPTION
see section 5.3 fa	r susface water information
C1 IB C. CONTAMINATION OF AIR C3 POPULATION POTENTIALLY AFFECTED: 16612	02 C OBSERVED (DATE:) POTENTIAL C ALLEGED 04 NARRATIVE DESCRIPTION
see section 5.4	tor contamination of air
©1 D. FIRE/EXPLOSIVE CONDITIONS ©3 POPULATION POTENTIALLY AFFECTED.	02 D OBSERVED (DATE) D POTENTIAL C ALLEGED 04 NARRATIVE DESCRIPTION
see section 5.5 f	for contamination of air
©1 19 E. DIRECT CONTACT ©3 POPULATION POTENTIALLY AFFECTED: 6000	02 D OBSERVED (DATE:) # POTENTIAL C ALLEGED 04 NARRATIVE DESCRIPTION
see section 5.6	for direct contact
©1 B F. CONTAMINATION OF SOIL ©3 AREA POTENTIALLY AFFECTED: (Acres)	02 SOBSERVED (DATE: 9.27.89) , POTENTIAL [ALLEGED 04 NARRATIVE DESCRIPTION
see section 5.8 for	- contamination of soil
©1 ® G. DRINKING WATER CONTAMINATION G3 POPULATION POTENTIALLY AFFECTED: 15000	02 © OBSERVED (DATE:) DEPOTENTIAL © ALLEGED 04 MARRATIVE DESCRIPTION
See Section 5.2	for drinking water contamination
©1 H. WORKER EXPOSURE/INJURY ©3 WORKERS POTENTIALLY AFFECTED: 250	02 D OBSERVED (DATE:) POTENTIAL C ALLEGED 04 NARRATIVE DESCRIPTION
pic documented worker	injury due to hazardous waste
©1 ■ 1. POPULATION EXPOSURE/INJURY (X3 POPULATION POTENTIALLY AFFECTED: 15800	02 D OBSERVED (DATE:) DOTENTIAL CALLEGED 04 MARRATIVE DESCRIPTION
See sections 5:24 5.4, f	5.6, for potential population exposure

\$EPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

I. IDENTIFICATION

O1 STATE O2 SITE NUMBER

TN D24 542 2653

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS IN DOC5432653
II. HAZARDOUS CONDITIONS AND INCIDENTS (CONTINUED)
01 E J DAVAGE TO FLORA 04 NARRATIVE DESCRIPTION COULD Stephially Occur through Confact with Conforminated Soil
documented by FIT.
01 & K DAMAGE TO FAUNA 02 © OBSERVED (DATE) POTENTIAL © ALLEGED 04 NAFFATIVE DESCRIPTION ACCOUNT THROUGH CONTACT WITH CONTAMINATED SOIT
documented by FIT.
01 D L CONTAMINATION OF FOOD CHAIN 02 DESERVED (DATE) POTENTIAL CALLEGED
or negrative description soil contaminants documented by FIT could potentially broadcountate in the local food Chain.
01 A M UNSTABLE CONTAINMENT OF WASTES (Sect. Aunolf: Standing sectors. Learning distants) 02 © OBSERVED (DATE
see sections 5.8, 5.3 and 5.6 for unstable containment of waste
01 TO NO DAMAGE TO OFFSITE PROPERTY 02 (DATE:) POTENTIAL CALLEGED 04 NAFRATIZE DESCRIPTION
see sections 5.2, 5.3 and 5.6 for damage to cff site property.
01 HO CONTAMINATION OF SEWERS, STORM DRAINS, WWTPS 02 DOBSERVED IDATE: 9-27-89) , POTENTIAL DALLEGED 04 NAPHATIVE DESCRIPTION TICL companyes were recoveled at concentrations above backyround levels at the edge of an inactive outlet to the river,
01 IP RLEGALUNAUTHORIZED DUMPING 02 DOBSERVED (DATE 9-89) [POTENTIAL [ALLEGED OA NA=ATIVE DESCRIPTION The company holds no permits for the disposal of any waste at the CCA site. Several waste disposal areas were observed on site. My Tony Parett of Walash, Indiana, complained in 1979 of illegal dumping by and of paper waste in his lack yard.
OF DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS Asbestes removal process currently in progress
145603 (0) 1 Emoved 1.
HI. TOWAL POPULATION POTENTIALLY AFFECTED:
IV COMMENTS
confaired hazardous waste drows were observed during the FIT inspection. The drows confaired hazardous waste and were soon to be removed according to the site refresentative. Spills on the ground from the frimary water treatment plant were observed on site.
V. SOURCES OF INFORMATION (Cre specific references e.g. state fees sample analysis reports)
state and FIT file information, Chicago, Illinois
SSI conducted on september 27, 1989

1	HP4	
W 47	_	

POTENTIAL HAZARDOUS WASTE SITE

	IFICATION
DISTATE	12 SITE NUMBER 1005432653

⊗EPA	SITE INSPECTION PART 4 - PERMIT AND DESCRIPTIVE INFORMATION				IN DOUSY38653	
II. PERMIT INFORMATION					· · · · · · · · · · · · · · · · · · ·	
DI TYPE OF FERMITISSUED	02 PERMIT NUMBER	03 DATE ISSUE	04 EXPIRATION DATE	05 COMMENTS		
CA NPDES	IN024741	5-2-8	5 2-28-90			
CB UIC	TIVOCTITI	- ~ ~	70	 		
CC AIR	85-05-90-0175	1-30-81	1 5-1-90	 -		
DD RCRA	102-03-10-0113	7-20-0	/ 	 		
C E RORA INTERIM STATUS	· · - · - · - · - · - · - · - · - · -		1	 		
CF SPCC PLAN	 			 		
☐ G STATE (Specify)				f		
EH LOCAL (S; ecry)		 		 		
C1 OTHER (Specify)			 	 -		
E J NONE	 		1 7	 		
III. SITE DESCRIPTION		L		<u> </u>		
	2 AMOUNT CEUS CE	MEASURE 04	TREATMENT (CHECK & CHARA	ere	05C"-€R	
C A SURFACE IMPOUNDMENT				,		
I E PILES			A INCENERATION B UNDERGROUNDINJ	ECTON	# A BUILDINGS ON SITE	
C DRUMS, ABOVE GROUND	Vickum		D. CHEMICAL PHYSICA			
E C TANK, ABOVE GROUND			D EIOLOGICAL	16	"	
E) E TANK, BELOW GROUND	7/1	I	E. WASTE OIL PROCES	SING	LE AFEA OF SITE	
B F LANDFILL	Vyknowy	[F SOLVENT RECOVER	Υ		
■ G LA '>DFARM	Unknown		☐ G OTHER RECYCLING RECOVERY 20			
M H OFEN DUMP	Outhown		H OTHER <u>Acrobic</u> free (ment 1500	Waste wat	er	
[] I OTHER			firee (ment	,		
treatment of water waste.						
IV. CONTAINMENT						
(1) CCATATINENT OF WASTES (Check one)	☐ B. MODERATE	C. INADE	QUATE, POOR	C D INSEC	URE, UNSOUND, DANGEROUS	
DZ DESCRIPTION OF DRUMS, DIKING, LINERS, BA	ARRIERS, ETC.					
po liners at the never had any positive of the descriptions several other dry	disposal area projective lin waste down was open and h	s white	e su opera e observe cueve o	tion tion ed on bserved	site on site	
V. ACCESSIBILITY						
of WASTE EASILY ACCESSIBLE: DYES (NO corced. Waste is dumped on the ground. Open largardors unstended on site.						
VI SOURCES OF INSORMATION (Francock) in least of state of the source of						
State and FIT file information, Chicago, Illiquis SSI conducted on Seftember 27, 1989						
SSI conducted un Jestember 21, 1989						

POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION			
DI STATE	D2 SITE NUMBER	•	
IN	DOUS 438653		

SEPA	PART 5 - WATER,	SITE INSPECTION DEMOGRAPHIC,		IMENTAL DATA	IN 1005 432653
II. DRINKING WATER SUPPLY					
01 TYPE OF DATA-ING SUPPLY (THIS BE SECURISE)		02 STATUS			03 DISTANCE TO SITE
SURFA	CE WELL	ENDANGERED	AFFECTED	MONITORED	. 1/-
COMMUNITY A. E	В. 🖶	A 🗆	B D	C 🖩	A(ml)
NON-COMMUNITY C D	D. 🐯	D 🖸	E D	F. D	B(mi)
III. GROUNDWATER					
DI GADUNDA ATERUSE IN VICATY &	neck one/				
■ A ONLY SOURCE FOR Effort N	(Other still) PS #v#rab	DUSTRIAL IRRIGATION		AL INDUSTRIAL IRRIGAT scurrer aug abier	TION DINOT USED, UNUSEABLE
02 POPULATION SERVED BY GROUND	WATER 15800	. و آن	3 DISTANCE TO NEA	REST DRINKING WATER I	WELL <u>2</u> (mi)
04 DEPTHIC GHOUNDWATER	05 DIRECTION OF GRO	UNDWATER FLOW DE	DEFITH TO ADJIFER OF CONCERN	R G7 PGTENTIAL YIEL OF AQUIFER	D OF SOLE SOURCE ADUIFER
30 _m	Assumed	south	20	m) Uykuwy	(and) L'YES IR NO
OR DESCRIPTION OF WELLS (residence as					
	4. 4.4.	· Λ.Λ.Λ.	xi wortely.	z miles s	ivithwest from
the site. They are	re 190' deep of	and driver w	fer from	rong fell 11	valley in flue
the ite Those draw	from a security surface. Must re	sidential well	age for draw for	ou the bed	valley in flie i miles southeast from a tely to feet from work aguifer.
TO he Deserted Made	wate ferment	ility of 1"	DISCHARGE AMEA	(moured we	ter may recharge
	ils	1.	T NO	ENTS piver du	ring low flow feiner
IV. SURFACE WATER					
01 SURFACE V.ATER USE (Check one)					
	A RESERVOIR, <u>RECEEATION</u> D.B. IRRIGATION, ECONOMICALLY D.C. COMMERCIAL, INDUSTRIAL D.D. NOT CURRENTLY USED DRIVING WATER SOURCE IMPORTANT RESOURCES				
02 AFFECTED POTENTIALLY AFFECTE	D BODIES OF WATER				
NAME				AFFECTED	DISTANCE TO SITE
	· -				Approximately 20 feit
Wabash Kive	<u>~</u>				num south property limitent
					(m)
V. DEMOGRAPHIC AND PROPE	RIVINFORMATION			000000000000000000000000000000000000000	
D1 TOTAL PCFULATION WITHIN				G2 DISTANCE TO NEARE	ST POPULATION
ONE (1, M LE OF SITE A. 6000 NO OFFERSONS	B. 15311	THREE (3) M	HLES OF SITE BUD H FERSONS		30 ft m
03: NUMBER OF BUILDINGS WITHIN TW	O (2) MILES OF SITE	04	DISTANCE TO NEA	REST OFF-SITE BUILDING	
\$	6000			30	of tomb
05 PCPULAT ON WITHIN VIONITY OF S	ITE (Bio can accepting division and				
			ny or site e.g. ivine iki a	de libe use à trabhaile aintrait aid	•
Densty Popula	fed residonti	cal ovea			j
'''					

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

LIDENTIFICATION OT STATE TO SITE NUMBER

MILIA		PART 5 - V	WATER, DEMOGRA	PHIC, AND	ENVIRO	NMENTAL DA	ATA LA	1 DULS438653
VI. ENVIRONMENT								
O1-ERNEABL TOFE								
D	A 10-6 - 10-8 c	m/sec DB.	. 10 ⁻⁴ - 10 ⁻⁶ cm/sec	\$ C. 10⁻⁴	– 10 ⁻³ cm	isec 🗆 D GR	EATER THAN 1	0~3 cm/sec
02 PERMEABLITY OF E	SEDROCK (Check one)							
	☐ A IMPERMEA (Less than 10 ⁻		B. RELATIVELY IMPERME (10 ⁻⁴ - 10 ⁻⁶ cm sec)	ABLE DC	RELATIVEL	LY PERMEABLE f cm sec)		PERMEABLE Non-16 ⁻² cm secj
03 DEFTHIC E: DROCK	· 0	4 DEPTH OF COP	NTAMINATED SOIL ZONE		C 5 SOIL ph	į		
≥ 100	(ft)	<u>]</u> 	Uyknown m		Vuk	(nowy_		
UE NET PRECE TATION	0	I ONE YEAR 24 I	HOUR RAINFALL	UE SLOPE SITE	E SLOPE	DIRECTION OF	SITE SLOPE	TERRAIN AVERAGE SLOPE
3	(in)		<u>2</u> (in)		0_%	011		5_%
SPILOSDIFC ENTIAL		10				1		
SITE IS IN	YEAR FLOO	DPLAIN	S TE IS ON BAI	RRIER ISLAN	D. COASTA	.L P'GH HAZ4FC	AREA, FIVER	TE FLOODWAY
11 DISTANCE TO WETL				12 DISTA	NCE TO CRIT	HCAL HABITAT : .		
EST	JARINE ,		OTHER				>3.0	. {mi;
AN	//1(mi)	B	>3 o (mi)	E	NDANGERE	ED SPECIES		
13 LAND USE & VICINIT	Y							
DISTANCE TO:		D.	ESIDENTIAL AREAS, NAT	TIONIAL ISTAT	L DADKE		ACDICULTU	DAL LANDE
COMMER	CIALINDUSTRIAL		FORESTS, OR WILD	ALIFE RESERV	VES	PRIME	AGRICULTU AG LAND	AG LAND
A _30	ft tom		в30 /	ft jour		c. Unki	<u>फारम</u> (mi)	D west border (mi)
14 DESCRIPTION OF SI	TE IN RELATION TO	SURROUNDING T	TOPOGRAPHY					
			i line			Λ 44	1.	A
Re	ter to	4- mi	le radius	my	14	Affe	zudix ,	A
,								
i								
1								
[
			ncez, e g., slata files, sample ana!					· · · · · · · · · · · · · · · · · · ·
Ctate	rend	FIT	tile ing september	forma;	tion	Chicag	0, I	: 6
	_ /	. ,	an Lounter	97 /	1900	•_	,	
777	. will	1c. f ed	September	6 1, 1	189			

SEPA		OTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT ART 6 - SAMPLE AND FIELD INFORMATION	1. IDENTIFICATION OT STATE OF SITE NUMBER IN DOUS 432.65!
II, SAMPLES TAKEN			
SAMPLE TYPE	01 NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO	O3 ESTIMATED DATE MESULTS AVAILABLE
GROUNDY ATER			
SURFACE WATER			
WASTE			
AIFI		See Section 3.4	
RUNOFF			
SPILI.			
_IK)28	6		presently available
VEGETATION			
OTHER Scalin ent	3		Presently Curvilable
III. FIELD MEASUREMENTS TA	KEN		
OI TYPE	02 COMMENTS		
OVA		o ppu	
Explising tor		0%"LEL	
Of we ter		21%	
Of we fer Hyuruy en cyanide uponitir		No alor change	
Rochation alert		No celarm	
IV. PHOTOGRAPHS AND MAPS			F
01 THE GROUND ARRIAL		02 IN CUSTODY OF GOODY & GUNDON WENT,	Luc.
03 MAPS BYES C NO 04 LOCATION C NO		voyment Inc. Chicago Il	
V. OTHER FIELD DATA COLLE	CTED (Provide narrative des	crotion)	
	Ļ	IA	
VI. SOURCES OF INFORMATIO			
State a	ud FI7	- file information Chica	yo, IL
SSI u	vas Gudu	file information Chris	1989
EPA FORM 2C70-13 (7-81)			

A PA	r	•	ARDOUS WASTE SITE	LIDENTIF		
SEPA			CTION REPORT	IN DO05432653		
		PART 7 - OWN	IER INFORMATION			
II. CURRENT OWNER(S)		CI C+ B NUMBER	PARENT COMPANY (# applicable)		09 D+B NUMBER	
Container Carporation			Je flerson Smurfit	Corp.		
1455 W. Factory St	reet	D4 SIC CODE	8188 Mary and Ave		11 SIC CODE	
	OG STATE	C7 ZIP CODE	J 12 CITY	"3 STATE	14 ZIP CODE	
	IN	46992 1224 B NUMBER	Clay for	Mo	63105 09 D+ B NJIMBER	
(IT NAME		CZ E G NOMBER	OU NAME		109 D. E. WOINBER	
(2 STIREET ADDRESS (F.O. Box, AFD # etc.)		D4 SIC CODE	10 STREET ADDRESS (F O Box RFL # BIC)		11 SIC CODE	
OS CITY :	06 STATE	67 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE	
C+ NAME		CZ D+ B NUMBER	OB NAME		09 D+ B NUMBER	
23 STREET ACCIRESS IF O Box AFD. OIC)		04 SIC CODE	10 STREET ADDRESS (F.C. Box RFD # etc.)		11 SIC CODE	
DE CITY	OE STATE	07 ZIF CODE	12 CITY	*3 STATE	14 ZIP CODE	
O1 NAME		C2 D+ B NUMBER	DR NAME		09 D+B NUMBER	
C3 STREET ADDRESS (P O Box, RFD #. elc.)		04 SIC CODE	10 STREET ADDRESS (P.O. Box. RFD # etc.)		11 SIC CODE	
05 CITY	06 STATE	C7 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE	
III. PREVIOUS OWNER(S) (Lis: most recent first)		L	IV. REALTY OWNER(S) IT ALT TO AST MOST	elen var	<u> </u>	
Dymon Match Corpora	fiva	02 D+B NUMBER	OI NAME UUKU		02 D+B NUMBER	
D3 STREET ADDRESS (P O Box RFD e, etc.)		04 SIC CODE	03 STREET ADDRESS IP O BOX RECT MEL	1004	D4 SIG CODE	
Unkown						
05 CITY	06 STATE	07 ZIP CODE	05 CITY	O€ STATE	07 ZIF CODE	
O1 NAME		C2 D+ B NUMBER	03 NAME		02 D+B NJMBER	
C3 STREET ADDRESS (P O BOA RFD P. ME)		04 SIC CODE	03 STREET ADDRESS (P.D. Box. AFD # esc.)		04 SIC CODE	
05 CITY	06 STATE	G7 ZIP CODE	05 CITY	CE STATE	07 ZIP CODE	
O1 NAME		02 D+B NUMBER	01 NAME		02 D+B NJMBER	
C3 STREET ADDRESS (F.O. Box, RFD #, etc.)		04 SIC CODE	03 STREET ADDRESS (F.O. Sca., RFC #, esc.)		04 SIC CODE	
C5CMY	OSTATE	07 ZIP CODE	05 CITY	CE STATE	D7 ZIP CODE	
V. SOURCES OF INFORMATION (Cno specific	relevances	e c. Siglé files sample analyse	s, reports)			
State and FIT	<i>T</i>	file in	formation Chicago.	IL		
SSI conducted	СИ	Seftember	formation Chicago, er 27 1989			
EPA FORM 2070-13 (7-81)						

	-	
-		PΔ

POTENTIAL HAZARDOUS WASTE SITE

1. IDENTIFICATION		
	02 SITE NUMBER	
IN	1005 438 653	

			TION REPORT OR INFORMATION	IN	205438653	
H. CURRENT OPERATO	R (Provide if different from	nonner)		OPERATOR'S PARENT COMPANY (# appr: abb)		
OI NAME Collfainer	Corporation	, 61	02 D+ B NUMBER	Tefferson Smurfit (11 D+ B NUMBER
03 STREET AWARESS IP 0 BO	a, RFD e, etc.)		04 SIC CODE	12 STREET ADDRESS (P O Box RFD# etc.)	13 SIC CODE	
OS CITY	Factory 31		07 ZIP CODE	8188 Marykund Ave	IIA CTATE	16 ZIP CODE
Wabash		IN		Clay for	MO	63105
1933 - Prescyt						
III. PREVIOUS OPERAT	L	ist Diovice on	ly Kid (ferent from owner)	PREVIOUS OPERATORS' PARENT CO	MPANIES #	* applicable)
DI NAVE DI NAVE Match CO STREET ADDRESS 10 BB			02 D+ B NUMBER	10 NAME Un KINDLUM 12 STREET AT THESS IP O BOX PICE OIC)		11 D+ B NULLEER
UN KOL	z RFD#, etc.)		04 SIC CODE	12 STREET ALIGHESS (P.O. Box RED. etc.)		13 SIC CODE
OS CITY	~ 1	OE STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIF CODE
DE YEARS OF OPERATION	OS NAME OF OWNER I		SPERIOD CONFOURTING			<u></u>
O. NAME	7,704	, (02 D+B NUMBER	10 NAME		11 D+ B NUMBER
00 STREET ADDRESS P 0 Bo	z, RFD #, etc.)		04 SIC CODE	12 STREET ADDRESS (P.O. Box. RFC + etc.)		13 SIC CODE
O4 CITY		06 STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIP CODE
GE YEARS OF OPERATION	09 NAME OF OWNER	DURING TH	S PERIOD		L	<u></u>
01 NAVIE			02 D+B NUMBER	10 NAME	· · · · ·	11 D+8 NUMBER
03 STREET ADDRESS : F 0 80	z, RFD Ø. etc.)		04 SIC CODE	12 STREET ADDRESS (P O Box. RFD P. BIC)	13 SIC CODE	
O! CITY		06 STATE	07 ZIP COD€	14 CITY	15 STATE	16 ZIP CODE
OL YEARS OF DPERATION	09 NAME OF OWNER	DURING TH	S PERIOD			
IV. SOURCES OF INFO						
State	and F	IT	file	ember 27, 1989	cago,	IL
SSI	coyduc,	f ed	on septe	ember 87, 1989		
				•		
					•	

11. CN-SITE GENERATOR CT HAVE CONTRIBUTE CONFORMATION COSTREET ACCHESS IPO BON MODERATOR USS W. Forctory SI OSCITY LILL BOSS 4		02 D+B NUMBER 04 SIC CODE			
CONTRIBUTE CONFORMATION CONTRIBUTED CONFORMATION CONTRIBUTION CONTRIBU					
Confusiner Corporation Confusiner Corporation Construction Confusiner Corporation Construction Confusiner Corporation Conf	treef	04 SIC CODE			
C35 REET & DRESS IPO BOX APPRIOR OR OF USS W. FOR CLOVY S	freef	04 SIC CODE			
OSCITY //L/ of	Freef ESTATE	, 1			
OS CITY //L/ C/	E STATE				
	+a.	D7 ZIP CODE			
LICE DOCUM	IN	46998			
III. OFF-SITE GENERATOR(S)					
O1 NAME		D2 C + B NUMBER	O' NAME		02 D+ B NUMBER
G3 STREET ADDRESS (P O Box, RFD 4, etc.)		04 SIC CODE	03 STHEET ADDRESS IP O BUL ALD O OIC I		To a const
(3 STREET ADDRESS (P D Box, HIDE, BIC)		U4 SIC CODE	OS STREET ADDRESS IN O BOX, AND P. OICT		04 SIC CODE
70	ESTATE	07 ZIP CODE	05 CITY	[05.57475]	07 ZIP CCDE
C6 01Y		or Zir Cobe		003.212	U7 ZIP CCDE
C1 NAME		02 D+B NUMBER	01 NAME	_l	02 D+ E NUMBER
j	ļ				
C3 STREET ADDRESS (FO But RED4. 410)	1	04 SIC CODE	03 STREET ADDRESS (P.O. BULL FFE etc.)		04 S C CODE
05 CTY 25	STATE	07 ZIP CODE	05 CITY	OF STATE	07 ZIP CODE
i i	ļ				
IV. TRANSPORTER(S)					
C1 NAME		02 D+B NUMBER	01 NAME		02 D+B NUMBER
Unknown					
Q3 STREET ADDRESS (P.O. Box, RFD #, etc.)		04 SIC CODE	03 STREET ADDRESS (P.C. Box AFD P. MC.)		04 SIC CODE
CS CITY N	E STATE	07 ZIP CODE	05 CITY	D6 STATE	07 ZIP CODE
<u> </u>			<u> </u>		
01 NAME]	02 D+B NUMBER	O1 NAME		02 D+ B NUMBER
	l	04 SIC CODE	03 678557 4000766		To second
(13 STREET ADDRESS (P O Box. RFD P, etc.)		SIC CODE	D3 STREET ADDRESS ,P O 60x, FFD . OIL J		04 SIC CODE
CIS CRY	ESTATEL	G7 ZIP CODE	05 CiTY	IOS STATE	07 ZIP CODE
US CAT		01 E. 005E	033111		0.5.
V. SOURCES OF INFORMATION (Cresseed). e	I		-1	_1	
			~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ 		,
State and F	IT	file 1	1 formation, Chricago	, I	-
Costs moved	101	/	September 27, 1989		
557 60400	ic ted	04	Je 104 61, 1989		
			·		
1					
}					
1					
j					1
1					
EPA FORM 2070-13 (7-81)		· · · · · · · · · · · · · · · · · · · ·			

⊕EPA	POTENTIAL HAZARDOUS WASTE SI SITE INSPECTION REPORT PART 10 - PAST RESPONSE ACTIVITIE	OI STATE OF SITE NUMBER
L PAST RESPONSE ACTIVITIES		
CH DA WATER SUPPLY CLOSED ON DESCRIPTION	Q2 DATE	O3 AGENCY
01 G B TEMPORARY WATER SUPPLY PRODE DESCRIPTION	/A	O3 AGENCY
DI I C PERMANENT WATER SUPPLY PRODUCTION	i	03 AGENCY
01 I D SPILLED MATERIAL REMOVED (14 DESCRIPTION /	02 DATE	03 AGENCY
01 DE CONTAMINATED SOIL REMOVED 04 DESURATION P/		C3 AGENCY
01 T F WESTE REPACKAGED 04 DESCRIPTION //	02 DATE	03 AGENCY
01 C. WASTE DISPOSED ELSEWHERE 04 DESCRIPTION	02 DATE	03 AGENCY
O1 Z H ON SITE BURIAL O4 DESCRIPTION	02 DATE	03 AGENCY
O1 21 IN SITU CHEMICAL TREATMENT OIL DESCRIPTION	O2 DATE	03 AGENCY
01 T.J. IN SITU BIOLOGICAL TREATMENT 04 DESCRIPTION	N/A	03 AGENCY
01 T.K. IN SITU PHYSICAL TREATMENT 04 DESCRIPTION	02 DATE	03 AGENCY
01 D.L. ENCAPSULATION 04 DESCRIPTION **Note: The content of the c	/A 02 DATE	O3 AGENCY
01 T.M. EMERGENCY WASTE TREATMENT 04 DESCRIPTION	02 DATE	03 AGENCY
DI C N CUTOFF WALLS 04 DESCRIPTION	02 DATE	03 AGENCY
01 TI O EMERGENCY DIKING SURFACE W 04 DESCRIPTION		03 AGENCY

02 DATE

02 DATE _

03 AGENCY ___

03 AGENCY

01 Z P CUTOFF TRENCHES:SUMP 04 DESCRIPTION

01 C O SUBSURFACE CUTOFF WALL 04 DESCRIPTION

9	F	PA
7/ 12	_	

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT, PART 10 - PAST RESPONSE ACTIVITIES

	TIFICATION
DI STATE	02 SITE NUMBER
IN	0005438653

WEFA	PART 10 - PAST RESPONSE ACTIVITIES	IN 0005438653
II PAST RESPONSE ACTIVITIES (Comment		
01 C. R. BARRIER WALLS CONSTRUCTED 04 DESCRIPTION	02 DATE	03 AGENCY
01 C S CAPPING COVERING 04 DESCRIPTION	N/14	03 ASENCY
01 IT BULK TANKAGE REPAIRED 04 DESCRIPTION	02 DATE	
01 T. U. GROUT CURTAIN CONSTRUCTED 04 DESCRIPTION	02 DATE	03 *SENCY
C1 T V BOTTOM SEALED C4 DESCRIPTION	N/A	05.4SEMCY
01 T. W. GAS CONTROL 04 DESCRIPTION	02 DATE	03 ±36 NCY
01 C X FIRE CONTROL 04 DESCRIPTION	02 DATE	
01 © Y LEACHATE TREATMENT 04 DESCRIPTION	N/A	
01 © Z. AREA EVACUATED 04 DESCRIPTION	P/A	OS AGENCY
01 D 1. ACCESS TO SITE RESTRICTED 04 DESCRIPTION	N/A	03 AGENCY
01 C 2. POPULATION RELOCATED 04 DESCRIPTION	N/A 02 DATE	03 AGENCY
01 (2) 3. OTHER REMEDIAL ACTIVITIES 04 DESCRIPTION	02 DATE	03 AGENCY
		•
III. SOURCES OF INFORMATION (Crescence	references, e.g., state files, sample ansiysis, reports)	
	FIT file information, lucted on Septembar	Chicago , IL
7 2 1 0040	September 1	L1, '10/

6	-	
Tre!	 -	$P\Delta$
■ 4'	L 1	

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION

1. IDENT	IFICATION
DY STATE	02 SITE NUMBER
IN	Dous 43865.

4)	ENFORCEMENT	INFORMATION
11.	ENTURCEMENT	IN ONE A HOR

D1 PAST REGULATORY ENFORCEMENT ACTION _ YES #NO

D2 DESCRIPTION OF FEDERAL, STATE, LOCAL REGULATORY ENFORCEMENT ACTION

N/1

III. SOURCES OF INFORMATION (Crespectic references, e.g., state lifes, sample analysis, reports)

State and FIT file information, Chicago, IC SSI conducted on September 27, 1989

APPENDIX C

FIT SITE PHOTOGRAPHS

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Container Corporation

PAGE / OF /3

U.S. EPA ID: IND005432653 TDD: F05-8710-070

PAN: FIN 06565B

DATE: >9-27-89

TIME: > 1240

DIRECTION OF

PHOTOGRAPH: > South

VEATHER

CONDITIONS: > 5 UMUY, 65°F

PHOTOGRAPHED BY: > Augelo

SAMPLE ID

(if applicable): > 51

DESCRIPTION: > Sample

> location for soil

> sample st



DATE: >9-27-89

TIME: > 1240

DIRECTION OF PHOTOGRAPH: > South

VEATHER

CONDITIONS: > SUMMY, 65°F

PHOTOGRAPHED BY: > Augelo Corpodinis

SAMPLE ID (if applicable):

DESCRIPTION: >



FIELD PHOTOGRAPHY LOG	SHEET
SITE NAME: Container Corporation	PAGE 2 OF 13
U.S. EPA ID: INDO05432653 TDD:F05-8710	-070 PAN: FIN 06565B
DATE: >9-27-89	
TIME: > 1200	The second secon
DIRECTION OF PHOTOGRAPH: > North	
VEATHER CONDITIONS: > 5 UMAY, 65°F	
PHOTOGRAPHED BY: > Corpodinic	ATT XXX S (S + 52 - 65 - 5
SAMPLE ID (if applicable): > SZ	Section 200 August 2.0 Section
DESCRIPTION: > Sample	
> location for soil	
> Sample 52	
>	
>	
>	
DATE: >9-27-89	
TIME: > 1200	
DIRECTION OF PHOTOGRAPH: > North	
VEATHER CONDITIONS: > SUYYY, 65°F	
>	
PHOTOGRAPHED BY: > Augelo Carfodinis	
SAMPLE ID (if applicable): > S2	
DESCRIPTION: >	

FIELD PHOTOGRAPHY LOG SHEET	
ITE NAME: Container Corporation	PAGE 3 OF 13
.s. EPA ID: IND005432653 TDD:F05-8710-070	PAN: FIN 06565B
ATE: >9-27-89	
THE: > 1225	
RECTION OF South	
NATHER NODITIONS: > Sugay, 65%	The season
NOTOGRAPHED BY: > Angelo dinis	SITE IND DOS 452 653 CITY WAS AS A TATE IN
AMPLE ID if applicable): > 53	DATE 9/27/87 THE TOOS AN PM
ESCRIPTION: > Sample	
location for soil	A WAR STAN
Sample 53	
	W. Car
ATE: >9-27-89	
INE: > 225	THE STATE OF THE S
DIRECTION OF	711111111111111111111111111111111111111
HOTOGRAPH:	SAL STATE
South	
EATHER ONDITIONS:	
Suyny, 65°F	
HOTOGRAPHED BY:	
Angelo Corpodinis	
SAMPLE ID .	
if applicable):	

DESCRIPTION: >

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Container Corporation

PAGE 4 OF 13

U.S. EPA ID: INDO05432653 TDD: F05-8710-070

PAN: FINO6565B

DATE: >9-27-89

TIME: > 1150

DIRECTION OF PHOTOGRAPH: > East

VEATHER

CONDITIONS: > 5 UMUY, 659

PHOTOGRAPHED BY: > Augeloinis

SAMPLE ID

(if applicable): > 54

DESCRIPTION: > Sample

> location for soil

> sample sy



DATE: >9-27-89

TIME: > 1/50

DIRECTION OF PHOTOGRAPH:

> East

VEATHER CONDITIONS: > Suyyy, 65°F


PHOTOGRAPHED BY:

> Augelo Carpodinis

SAMPLE ID

(if applicable):

DESCRIPTION: >



_	Contraction of the last of the	_		THE RESERVE OF THE PERSON NAMED IN
FIELD	PHOTOGR	APHY	LOG	SHEET

SITE NAME: Container Corporation

PAGE 5 OF 13

U.S. EPA ID: INDO05432653 TDD: F05-8710-070

PAN: FIN 06565B

DATE: >9-27-89

TIME: > //55

DIRECTION OF

PHOTOGRAPH: > East

VEATHER

CONDITIONS: > Suyuy, 65%

PHOTOGRAPHED BY: > Angelo > Carpodinis

SAMPLE ID

(if applicable): > 55

DESCRIPTION: > Sample

> location for soil

> sample S5

>



DATE: >9-27-89

TIME: > 1155

DIRECTION OF PHOTOGRAPH:

> East

VEATHER CONDITIONS:

> SUYMY, 65°F

>

PHOTOGRAPHED BY:

> Augelo Carpodinis

SAMPLE ID

(if applicable):

\$5

DESCRIPTION: >



_		FIELD PHOTOGRAPH	Y LOG SHEET		
SITE NAME:	Container	Corporation	1	PAGE 6 OF 13	
U.S. EPA ID	: INDO054320	53 TDD: F05-	8710 - 070	PAN: FIN 06	565B
DATE: >9-5	27-89				
TIME: > /3	300	THE TOTAL	(被) 整个		
DIRECTION O PHOTOGRAPH:	> SouthEast		大型		
VEATHER CONDITIONS:	> 5 UMMY, 65	F	SITETIND ODS 433 (553) CITY Wolds STAIN N DATE OF		
	D BY: >Larry Lu	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	TIME 1300 AM		
SAMPLE ID	ble): > 57	A STATE OF THE STA		No.	
DESCRIPTION	1: > sample		1.49	W. A. S.	
	1 for soil			THE PARTY OF THE P	
> sample	57		6		
>			WAR TO	They are	
>				The state of the s	
>					
DATE: >9'	97-89		No.		
TIME: > 130					
DIRECTION O		11	建立 使示		
PHOTOGRAPH:					
VEATHER	,	The same of	可以		
> Suyyy,	65°F				
>					
PHOTOGRAPHI	ED BY:	U.S. The			
> Larry L	veck	基於			
SAMPLE ID (if applica	able):			The	
> 57		See Line			
DESCRIPTION	N: >				
> Backgrou	und photo for	soil sample	57		

FIELD PHOTOGRA	PHY LOG SHEET
SITE NAME: Container Corporati	04 PAGE 7 OF 13
U.S. EPA ID: INDO05432653 TDD: F09	
DATE: >9-27-89	
TIHE: > 1305	CERT THE LEW TO A STATE OF THE LAND
DIRECTION OF PHOTOGRAPH: > North	
VEATHER CONDITIONS: > 5 UMMY, 65°F	TO THE PARTY OF TH
PHOTOGRAPHED BY: >Tim Dayzer	WHETEO COS WEE AST
SAMPLE ID (if applicable): > 58	STATE WALKEN STATE AN
DESCRIPTION: > Sample	
> location for soil	
> sample 58	
>	
>	
>	
DATE: >9-27-89	
TIME: > 1305	
DIRECTION OF PHOTOGRAPH: > North	
VEATHER CONDITIONS: > SUYNY, 65°F	
>	
PHOTOGRAPHED BY: > Tim Dayzer	
SAMPLE ID (if applicable): > \$\sigma 8\$	
DESCRIPTION: >	
> Background photo for soil so	ruple 58

SITE NAME: Container Corporation PAGE 8 OF 13 J.S. EPA ID: INDO05432653 TDD: F05-8710-070 PAN: FIN 06565 B PATE: >9-27-89 ITHE: > 1250 DIRECTION OF PHOTOGRAPHE: > East PHOTOGRAPHED BY: > Tim Danzer SAMPLE ID (if applicable): > 59 DESCRIPTION: > Sample Discation for soil Sample S9 DATE: >9-27-89 TIME: > 1250		FIELD PHO	TOGRAPHY LOG SHEET		
DATE: >9-27-89 CHE: > 1250 CHECTION OF PHOTOGRAPH: > Last CITYWOLASA, STATE IN SAMPLE S9 CHOTOGRAPHED BY: > TIM Danzer SAMPLE ID (if applicable): > S9 DESCRIPTION: > Sample > location for soil > Sample S9 DATE: >9-27-89	SITE NAME: Cout	ainer Corpor	ration	PAGE 8 OF 13	
DIRECTION OF PHOTOGRAPH: > East VEATHER CONDITIONS: > SUMMY, 65 PHOTOGRAPHED BY: > TIM Danger SAMPLE ID (if applicable): > Sq DESCRIPTION: > Sample Docation for soil Sample S9 DATE: > 9-27-89	I.S. EPA ID: INDO	5432653 TOD	:F05-8710 -070	PAN: FIN 065	65B
PHOTOGRAPH: > Cast VEATHER CONDITIONS: > Suguy, 65 PHOTOGRAPHED BY: > Tim Danger SAMPLE ID (if applicable): > S9 DESCRIPTION: > Sample > Sample S9 DATE: > 9-27-89	DATE: >9-27-89				1
PHOTOGRAPH: > East VEATHER CONDITIONS: > SUMMY, 65 PHOTOGRAPHED BY: > Tim Danger SAMPLE ID (if applicable): > S9 DESCRIPTION: > Sample Docation for soil Sample S9 DATE: > 9-27-89	THE: > 1250				
PHOTOGRAPHED BY: > Tim Domzer SAMPLE ID Gif applicable): > Sq Description: > Sample Docation for soil Sample S9 Date: >9-27-89	DIRECTION OF PHOTOGRAPH: > tast				
PHOTOGRAPHED BY: > Tim Danzer SAMPLE ID (if applicable): > S9 DESCRIPTION: > Sample location for soil Sample S9 DATE: > 9-27-89		ицу, 65	J.	SAMPLE 59 DATE 9/21/89	
DESCRIPTION: > Sample location for soil Sample S9 Sample S9 DATE: >9-27-89	PHOTOGRAPHED BY: >	Tim Danzer		TIME TOO AM PM	
DATE: >9-27-89	SAMPLE ID (if applicable): >	59			
Sample S9 DATE: >9-27-89	1	V			
	>				
TIME: > 1250	DATE: >9-27-89	EGW.			
	TIME: > 1250				

DIRECTION OF PHOTOGRAPH:

> East

VEATHER
CONDITIONS:
> Suyy, 65°F

> Tim Dayzer

SAMPLE ID
(if applicable):
> S9

DESCRIPTION: >



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Container Corporation

PAGE 9 OF 13

U.S. EPA ID: INDO05432653 TDD:F05-8710-070

PAN: FIN 06565B

DATE: >9-27-89

TIME: > 1457

DIRECTION OF

PHOTOGRAPH: > Southtast

VEATHER

CONDITIONS: > Suyuy 50°F

PHOTOGRAPHED BY: > Con Activis

SAMPLE ID

(if applicable): >

DESCRIPTION: > Hazarolous

> Waste Drums located

> East from layours.



DATE: >9-27-89

TIME: > 1450

DIRECTION OF PHOTOGRAPH: > South west

VEATHER
CONDITIONS:
> SUYYY, 65°F

PHOTOGRAPHED BY: > Augelo Confodings

SAMPLE ID (if applicable):

DESCRIPTION: >



> Waste Water spill next to the primary water treatment plant.

		FIELD PHOTO	OGRAPHY LOG	SHEET		
SITE NAME:	Container	Corpora	ation		PAGE 10 OF	13
U.S. EPA II	: INDO054320	653 TDD:	F05-8710	-070	PAN: FIN	06565 E
DATE: >9-	27-89					
TIME: > /4	453	PART		HH		1 33
DIRECTION OF PHOTOGRAPH:	SouthWest	Tak.				
VEATHER		or and a second			WAS	Sign



DATE: >9-27-89

TIME: > 1502

> plant.

DIRECTION OF PHOTOGRAPH:

> North

VEATHER
CONDITIONS:
> Suyuy, 65°F


PHOTOGRAPHED BY:

> Aurelo Carpodines

SAMPLE ID

(if applicable):

DESCRIPTION: >



> Mostly empty drove stacked wext to main building.

SITE NAME: Container Corporation	PAGE // OF /3
J.S. EPA ID: INDO05432653 TDD:F05-8710-070	PAN: FIN 06 565 B
DATE: >9-27-89	
TIHE: > 1442	
DIRECTION OF PHOTOGRAPH: > North last	The state of the s
VEATHER CONDITIONS: > 5 UMUY, 65°F	
PHOTOGRAPHED BY: > Augelo S	
SAMPLE ID (if applicable): >	
DESCRIPTION: >	
Uncovered paper piles	
	그리아 얼마나 아이를 되었다면 하는 사람들이 얼마나 되는 것이다.
<u> </u>	
DATE: >9'-27-89	
DATE: >9-27-89 TIME: > 1505	
DIRECTION OF PHOTOGRAPH:	
TIME: > 1505 DIRECTION OF	
DIRECTION OF PHOTOGRAPH: > West VEATHER CONDITIONS:	
DIRECTION OF PHOTOGRAPH: > West	
DIRECTION OF PHOTOGRAPH: > West VEATHER CONDITIONS: > SUMMY, 65°F	
DIRECTION OF PHOTOGRAPH: > West VEATHER CONDITIONS:	
DIRECTION OF PHOTOGRAPH: > West VEATHER CONDITIONS: > SUMMY, 65°F > PHOTOGRAPHED BY:	

7/3

FIELL	PHOTOGRAPHY LOG SHEET		
SITE NAME: Container Co	rporation	PAGE /2 OF /3	
U.S. EPA ID: INDO05432653		PAN: FIN 06565	В
DATE: >9-27-89			
TIME: > 1443			
DIRECTION OF PHOTOGRAPH: > South tast			A STATE OF THE STA
VEATHER CONDITIONS: > 5 UMAY, 65%	TO AS		
PHOTOGRAPHED BY: > Caur Podinis	TAUL	n de la companya della companya della companya de la companya della companya dell	20.
SAMPLE ID (if applicable): >			
DESCRIPTION: > Wind blown		更多大量	
> paper by the ground.			
> .		The Tark	
>			
>			
DATE: >9-27-89			
TIME: > 1444			
DIRECTION OF PHOTOGRAPH: > North		Y	
VEATHER CONDITIONS: > Suggy, 65°F			
>	- {·		
PHOTOGRAPHED BY: > Augelo Confodinis	~ ~		
SAMPLE ID (if applicable):			

DESCRIPTION: >

> Paper piles next to main building walls.

CTOD MAND. /	C - Dara Line	BACR 13 AR 12
SITE NAME: Container		PAGE /3 OF /3
J.S. EPA ID: IND0054320	653 TDD: F05-8710-070	PAN: FIN 06565
DATE: >9-27-89		
TIME: > 1508		who are
DIRECTION OF PHOTOGRAPH: > West		
VEATHER CONDITIONS: > 5 UMAY 65	· F	
PHOTOGRAPHED BY: > Augelo Conditions: > 5 Uyuy, 65 PHOTOGRAPHED BY: > Augelo	100	
SAMPLE ID (if applicable): >		
DESCRIPTION: > Unavered of		
> equipmet dunget		
> in a northwest	L CONTRACTOR OF THE PARTY OF TH	
> part of the site.		
>		
>		
DATE: >9-27-89		
TIME: > /230		
		The second of
DIRECTION OF		
DIRECTION OF PHOTOGRAPH: > North		
PHOTOGRAPH:		
PHOTOGRAPH: > North VEATHER CONDITIONS:		
PHOTOGRAPH: > North VEATHER CONDITIONS.		
PHOTOGRAPH: > North VEATHER CONDITIONS		
PHOTOGRAPH: Neather Conditions: Suyny, 65° F PHOTOGRAPHED BY:		
PHOTOGRAPH: Neather Conditions: Suyny, 65° F PHOTOGRAPHED BY:		
PHOTOGRAPH: > North VEATHER CONDITIONS: > SUYMY, 65°F > PHOTOGRAPHED BY: > Angelo Compodinis SAMPLE ID		
PHOTOGRAPH: > North VEATHER CONDITIONS: > SUYMY, 65°F > PHOTOGRAPHED BY: > Aygelo Confodinis		

APPENDIX D

U.S. EPA TARGET COMPOUND LIST AND

TARGET ANALYTE LIST

QUANTITATION/DETECTION LIMITS

ADDENDUM A

ROUTINE ANALYTICAL SERVICES
CONTRACT REQUIRED DETECTION AND QUANTITATION LIHITS

_

A 1

Contract Laboratory Program Target Compound List Quantitation Limits

			SOIL SEDIHENT
COHPOUND	CAS #	VATER	SLUDGE
Chloromethane	74-87-3	10 ug/L	10 ug/Kg
Bromomethane	74-83-9	10	10
Vinyl chloride	75-01-4	10	10
Chloroethane	75-00-3	10	10
Hethylene chloride	75-09-2	5	5
Acetone	67-64-1	10	5
Carbon disulfide	75-15-0	5 ·	5
1,1-dichloroethene	75-35-4	5	\$
1,1-dichloroethane	75-34-3	5	5
1,2-dichloroethene (total)	540-59-0	S	5
Chloroform Chloroform	67-66-3	5	5
1,2-dichloroethane	107-06-2	5	5
2-butanone (HEK)	78-93-3	10	10 -
1,1,1-trichloroethane	71-55-6	5	5
Carbon tetrachloride	56-23-5	5	5
Vinyl acetate	108-05-4	10	10
Bromodichloromethane	75-27-4	5	5
1,2-dichloropropane	78-87-5	5	
cis-1,3-dichloropropene	10061-01-5	5	5 5 5 5
Trichloroethene	79-01-6	5	5
Dibromochloromethane	124-48-1	5	5
1,1,2-trichloroethane	79-00-5	5 5 5 5	5
Benzene	71-43-2	5	5
Trans-1,3-dichloropropene	10061-02-6		5
Bromoform	75-25-2	5	5
4-Hethyl-2-pentanone	108-10-1	10	10
2-Hexanone	591-78-6	10	10
Tetrachloroethene	127-18-4	5	5
Tolene	108-88-3	5	5
1,1,2,2-tetrachloroethane	79-34-5	5	5
Chlorobenzene	108-90-7	5 5 5	5 5 5 5 5
Ethyl benzene	100-41-4		5
Styrene	100-42-5	5	5
Xylenes (total)	1330-20-7	5	5

Table A
Contract Laboratory Program
Target Compound List
Semivolatiles Quantitation Limits

			SOIL SEDIHENT
COHPOUND	CAS #	VATER	SLUDGE
Phenol	108-95-2	10 ug/L	330 447/84
bis(2-Chloroethyl) ether	111-44-4	10 08/2	330 ug/Kg 330
2-Chlorophenol	95-57-8	· 10	330
1,3-Dichlorobenzene	541-73-1	10	330
1.4-Dichlorobenzene	106-46-7	10	330
Benzyl Alcohol	100-51-6	10	330
1,2-Dichlorobenzene	95-50-1	10	330
2-Hethylphenol	95-48-7	10 ·	330
bis(2-Chloroisopropyl) ether	108-60-1	10	330
4-Methylphenol	106-44-5	10	330
N-Nitroso-di-n-dipropylamine		10	330
Hexachloroethane	67-72-1	10	330
Nitrobenzene	98-95-3	10	330
Isophorone	78-59 -1	10	330.
2-Nitrophenol	88-75-5	10	330
2,4-Dimethylphenol	105-67-9	10	330
Benzoic Acid	65-85-0	50	1600
bis(2-Chloroethoxy) methane	111-91-1	10	330
2,4-Dichlorophenol	120-83-2	10	330
1,2,4-Trichlorobenzene	120-82-1	10	330
Naphthalene	91-20-3	10	330
4-Chloroaniline	106-47-8	10	330
Hexachlorobutadiene	87-68-3	10	300
4-Chloro-3-methylphenol	59-50-7	10	330
2-Hethylnaphthalene	91-57-6	10	330
Hexachlorocyclopentadiene	77-47-4	10	330
2,4,6-Trichlorophesol	88-06-2	10	330
2,4,5-Trichlorophesol	95-95-4	50	1600
2-Chloronaphthalene	91-58-7	10	330
2-Nitroaniline	88-74-4	50	1600
Dimethylphthalate	131-11-3	10	330
Acenaphthylene	208-96-8	10	330
2,6-Dinitrotoluene	606-20-2	10	330
3-Nitroaniline	99-09-2	50	1600
Acenaphthene	83-32-9	10	330
2,4-Dinitrophenol	51-28-5	50	1600
4-Nitrophenol	100-02-7	50	1600
Dibenzofuran	132-64-9	10	330
2,4-Dinitrotoluene	121-14-2	10	330
Diethylphthalate	84-66-2	10	
4-Chlorophenyl-phenyl ether	7005-72-3	10	330
· Justich a pulsa celler	.005-12-3	10	330

6 7

בט, ביי יים

Table A
Contract Laboratory Program .
Target Compound List
Semivolatiles Quantitation Limits

		<u>:</u>	SOIL SLUDGE
COHPOUND	CAS #	VATER	SEDIHENT
Fluorene	86-73-7	10 ug/L	330 ug/Kg
4-Nitroaniline	100-01-6	50	1600
4,6-Dinitro-2-methylphenol	534-52-1	50	1600
N-nitrosodiphenylamine	86-30-6	10	330
4-Bromophenyl-phenylether	101-55-3	10	330
Bexachlorobenzene	118-74-1	10	330
Pentachlorophenol	87-86-5	50	1600
Phenanthrene	85-01-8	10	330
Anthracene	120-12-7	10	330
Di-n-butylphthalate	84-74-2	10	330-
Fluoranthene	206-44-0	10	330
Pyrene	129-00-0	10	330
Butylbenzylphthalate	85-68-7	10	330
3,3'-Dichlorobenzidine	91-94-1	20	660
Benzo(a)anthracene	56-55-3	10	330
Chrysene	218-01-9	10	330
bis(2-Ethylhexyl)phthalate	117-81-7	10	330
Di-n-octylphthalate	117-84-0	10	330
Benzo(b)fluoranthene	205-99-2	10	330
Benzo(k)fluoranthene	207-08-9	10	330
Benzo(a)pyrene	50-32-8	10	330
Indeno(1,2,3-cd)pyrene	193-39-5	10	330
Dibenz(a,h)anthracene	53-70-3	10	330
Benzo(g,h,1)perylene	191-24-2	10	330

7~~ 7 47

Table A
Contract Laboratory Program
Target Compound List
Pesticide and PCB Quantitation Limits

			SOIL SEDIHENT
COHPOUND	CAS #	VATER	SLUDGE
alpha-BHC	319-84-6	0.05 ug/L	8 ug/Kg
beta-BRC	319-85-7	0.05	8
delta-BHC	319-86-8	. 0.05	8
gamma-BHC (Lindane)	58-89-9	0.05	8
Heptachlor	76-44-8	0.05	8
Aldrin	309-00-2	0.05	8 -
Heptachlor epoxide	1024-57-3	0.05	8
Endosulfan I	959-98-8	0.05	8
Dieldrin	60-57-1	0.10	16
4,4'-DDE	72-55-9	0.10	16
Endrin	72-20-8	0.10	16
Endosulfan II	33213-65-9	0.10	16
4,4'-DDD	72-54-8	0.10	16 .
Endosulfan sulfate	1031-07-8	0.10	16
4.4'-DDT	50-29-3	0.10	16
Hethoxychlor (Hariate)	72-43-5	0.5	80
Endrin ketone	53494-70-5	0.10	16
alpha-Chlordane	5103-71-9	0.5	80
gamma-chlordane	5103-74-2	0.5	80
Toxaphene	8001-35-2	1.0	160
AROCLOR-1016	12674-11-2	0.5	80
AROCLOR-1221	11104-28-2	0.5	80
AROCLOR-1232	11141-16-5	0.5	80
AROCLOR-1242	53469-21-9	0.5	80
AROCLOR-1248	12672-29-6	0.5	80
AROCLOR-1254	11097-69-1	1.0	160
AROCLOR-1260	11096-82-5	1.0	160

Table A (Cont.)

CONTRACT LABORATORY PROGRAM

TARGET ANALYTE LIST (TAL)

INORGANIC DETECTION LIMITS

		Dete	ction Limits
Compound	Procedure	Water (µg/L)	Soil Sediment Sludge (mg/kg)
aluminum	ICP	200	40
antimony	furnace	60	2.4
arsenic	furnace	10	2
barium	ICP	200	40
beryllium	ICP	5	1
cadmium	ICP	5	1
calcium	ICP	5,000	1,000
chromium	ICP	10	2
cobalt	ICP	50	10
copper	ICP	25	5
iron	ICP	100	20
lead	furnace	5	1
magnesium	ICP	5,000	1,000
manganese	ICP	15	3
mercury	cold vapor	0.2	0.008
nickel	ICP	40	8
potassium	ICP	5,000	1,000
selenium	furnace	5	1
silver	ICP	10	2
sodium	ICP	5,000	1,000
thallium	furnace	10	2
tin	ICP	40	.8
vanadium	ICP	50	10
zinc	ICP	20	4
cyanide	color	10	2

3767:1

APPENDIX E

WELL LOGS OF THE AREA OF THE SITE

DIVISION OF WATER RESOURCES INDIANA DEPARTMENT OF CONSERVATION 311 WEST WASHINGTON STREET INDIANAPOLIS, INDIANA

WATER WELL RECORD

Non-responsive, well locations
ounty in which well was dr
ongressional township:
escribe in your own words
r distinctive landmarks:
Non-recooncive PII
Non-responsive, Plant Address:
ame of Well Drilling Contractor: Nath Muly & Son
ddress:
wme of Drilling Equipment Operator:
INFORMATION ON THE WELL
ompleted depth of well: ft. Date well was completed: July 12-/62
nameter of outside casing or drive pipe:Length:
iameter of inside casing or liner:Length:
iameter of Screen: 14 Length: 3 - Slot size: 12
pe of Well: Drilled Gravel Pack Driven Other
se of Well: For home For industry For public supply Stock
ethod of Drilling: Cable Tools Rotary Rev. Rotary Jet Driven
tatic water level in completed well (Distance from ground to water level) 20 ft.
iler Test: Hours testedRateg.p.m. Drawdownft. (Difference between
static level and water mping Test: Hours tested Rate 200 g.p. Drawdown ft. level at end of test
Signature Halfile Kluty
Date

WATER WELL LOG				
FORMACIONS (Color, type of material, hardness, etc.)	From	To	Topo. P	COUNTY:
Jail + Sando Clay		10	t By	; ;;
2.11.19 pack of time (+18'	10	27	0.71	
minutely sand 432'	1.7	li C'	1 ()	•
-fully rapel france x41	100	4-4	by:	
			well]	
			777	
				FOR (Well
			70	R ADMI 1 Dril
				ADMINISTRATIV
			Courthouse Field Loca Placed in 1	ADMINISTRATIVE USE Driller does not fi
			0 1	VE US
			accepted w/ thouse Loc. 1 Located ed in Master	SE ONLY fill
			ter c	
			By — By — Well Lo	
			m ŭ	
			g File	
			Date Date Date Date	5
EMARKS:				
This is not a modeltation	Jul	<i>t</i> - (
Lat at all supply Then need				

INSTRUCTIONS

This Water Well Record form is designed to record the most essential data concerning a vater well. We request that you be as accurate as possible in recording this information as t may be of great assistance in the planning and development of new water supplies.

An accurate location of the well is equally as important as an accurate well log.

lease include all information possible in the space provided for well location.

As specified in Chapter 6 of the Acts of 1959, a copy of this report must be submitted athin thirty days after the completion of a well to the Division of Water Resources, Indiana spartment of Conservation, 311 West Washington Street, Indianapolis, Indiana.

LAYNE-NORTHERN COM ANY

TEST MISHAWAKA, INDIANA				
PERMANENT		Job 1	No. <u>1911</u>	206
WELL LOG No. 64 A CITY Wabash	C	ounty	<u>Wabash</u>	
Owner City Later Dept.	Тс	wnship	Noble	
	Se	clion		
Location .			iana	
From Land Descriptionft. East and				
From Street or Road 350 E. of State Rd. 13 and 150	O' N. of	rance l	₹₫	
	FROM	I NATURAI	GROUND	LEVEL
FORMATION FOUND — DESCRIBE FULLY	Depth to Top of Stratum	Depth to Bottom of Stratum	Thickness of Stratum	Static Nater Leval
Top Soil	1	3	3	
Brown Sandy Clay	3	10	7	
Grey Clay and gravel	10	20	10	
Grey sand and gravel x/5'	20	35	15	
Brown wire sandy clay	35	37	2	
Brown clay and gravel	37	Lio	3	
Brown sandy clay	40	55	15	<u> </u>
Brown sand and gravel (clay balls)	55	60	5	
Brown fine muddy sand	60	62	2	
Brown sandy clay	62	77	15	
Brown sand and gravel (coarse)	77	91	14	2
Brown gravel and clay	91	96	5	
Brown sand and gravel	96_	100	1_1	_21_
Brown fine sand 785 (100	111	11	2]_
Brown Clay / 38	111	118	7	
Brown coarse sand and gravel 677	118	124	66	21_
Brown gravel and clay	124	130	6	
Brown sandy clay	130	136	6	: !
Brown sand and gravel	136	138	2	
Lime rock	138			·
Screened in 141 thickness of stratum 751 to 901				
inch diameter hole drilled by 🔁 Cable T Pipe left in hole 79 * 7" of 6"	'ool [] Rolar	y 🗌 Jettir	ng	

Date Started 7-2-1964 Finished 7-21-64 Robert T. Hayfield

STATE ÖFFICE BUILDING INDIANAPOLIS, INDIANA 46204 Telephone 633-5267 Area Code 317

WATER WELL RECORD

WELL LOCATION (Fill in completely - Refer to instruction sheet)	
County in which well was drilled	
	•
NAME OF WELL OWNER and/or BUILDING CONTRACTOR	
Well Owner Address	
Building Contractor Address	•
Name of Well Drilling Contractor: Smith	
Address Sagro, Ind	
Name of Drilling Equipment Operator:	
WELL INFORMATION	ý.
Depth of well: 2 melo 129 Date well was completed:	
Diameter of casing or drive pipe: Total Length:	-
Diameter of liner (if used): Total Length:	•
Diameter of Screen: Length: Slot Size:	· · · · · · · · · · · · · · · · · · ·
Type of Well: Drilled Gravel Pack Driven Other	
Use of Well: For Home Derico For Industry For Public Supply	Stock 🔲
Method of Drilling: Cable Tools : Rotary Rev. Rotary : Jet : Bucket I	Rig 🔲
Static water level in completed well (Distance from ground to water level)	feet
	own is the difference
	n static level and water end of test)
Signature Copied grow drillers Date 3/28/78	log Wic
Date 3/28/78	

WATER WELL LOG

FORMATIONS (Color, type of material, hardness, etc.)	From	To	የ	71	-i C
Course gravel			Courthouse Location By Location accepted w/o verification by Clark out: A	Field Located	COUNTY_
<i>(</i>)			accep	cated	P
		0	pted w		
			n By w/o ver	Ву	2
			ificati		
			on by		Mask
			e Dan	Date	
) m of		Non-responsive, well locations
		0	E P		
•			8		FC
			8/62		FOR ADMINISTRATIVE USE ONLY (Well driller does not fill aux)
					ADMINISTRAT
					TRA
					NVE
			_Ft S	7	TVE USE ON
			Ft E of WL	Ft N of SL	NLY
			,	•	
			Bed Aqu	Dep	
			Bedrock elevation Aquifer elevation	Depth to bedrock	
, i		-	levatio evatio	bedro	
				;	` `
		······································			
			و	1	S
			Lot Number		Subdivision Name
			, X		ision l
					Z m
				1.	1

DIVISION OF WATER RESOURCES INDIANA DEPARTMENT OF CONSERVATION 311 WEST WASHINGTON STREET INDIANAPOLIS, INDIANA

WATER WELL RECORD

County in which well



INTURMATION	ON APPT POCYLION	31,4
	_	
o roch	oncivo wo	II Iocotior

Congressional township
Describe in your own v
or distinctive landman
Name of owner: Non-responsive, PII
Name of Well Drilling Contractor:
Address: (3 3)
Name of Drilling Equipment Operator:
INFORMATION ON THE WELL
Completed depth of well: 5 ft. Date well was completed: 5 ft.
Diameter of inside casing or liner:Length:
Diameter of Screen:Length:Slot size:
Type of Well: Drilled Gravel Pack Driven Other
Use of Well: For home For industry For public supply Stock
Method of Drilling: Cable Tools Rotary Rev. Rotary Jet Driven []
Static water level in completed well (Distance from ground to water level) /2 ft.
Bailer Test: Hours tested Rate g.p.m. Drawdown ft. (Difference between
Pumping Test: Hours tested Rate g.p.m. Drawdown ft. level at end of test)
Signature 1/1 1/2/ 125

FOR WELL LOG SPACE USE REVERSE SIDE OF THIS SHEET

WATER WELL LOG

WATER WELL LOG	<u></u>					
FORMATIONS (Color, type of material, hardness, etc.)	From	То	Well I	El. of Depth t	Topo. Map:	COUNTY:
e entre	0	1,7	1	င်က္ခ	Мар:	Y:
12.0000	18	77	processed by:	H		Non-responsive
Maniational	1,133	5 %	ssed	surface at well:	4	
		<u> </u>	P &	e at	habash	
		ļ	60	wel	503	
		 	Dea	1:	5	
			7	1	k E	
			4	2000		FOR
			W	7		
	<u> </u>	<u> </u>	`			ADMINISTRATIVE USE
			Pla	- Cou	Loc	STRATI
		 	ced	irtho ild I	3. AC	CIVE U
			Placed in Master Well	Courthouse Loc. Field Located	Loc. accepted w/o verification	USE
	<u> </u>	 	laste	Loc.	ò £	JSE ONLY
			r We		1/0 V	
			-{	By 7	erif	(1)
		 	og F	R	loat	(1)
			ile		ion	. 7
		 	Date	Date Date	Yes -	cito
FEMARKS:		 	1 1	77	No No	a
			1	70	1	4 3
			1 3	55	11	2. 2
<u></u>	L		<u> </u>	,		

INSTRUCTIONS

This Water Well Record form is designed to record the most essential data concerning a water well. We request that you be as accurate as possible in recording this information as it may be of great assistance in the planning and development of new water supplies.

An accurate location of the well is equally as important as an accurate well log.

Please include all information possible in the space provided for well location.

As specified in Chapter 6 of the Acts of 1959, a copy of this report must be submitted within thirty days after the completion of a well to the Division of Water Resources, Indiana Department of Conservation, 311 West Washington Street, Indianapolis, Indiana.

W

DIVISION OF WATER

DEPARTMENT OF NATURAL RESOURCES, STATE OF INDIANA

WLE

STATE OFFICE BUILDING INDIANAPOLIS, INDIANA 46209

MElrose 3-6757

WATER WELL RECORD

Non-responsive, well locations

·
Name of owner Non-responsive, PII
Name of Well Drilling Contractor: / ngil 77 with
Address: R3 Walloch Ind.
Name of Drilling Equipment Operator:
INFORMATION ON THE WELL
Completed depth of well: 199 ft. Date well was completed: 200 9 1970
Diameter of outside casing or drive pipe: # Length: 109
Diameter of inside casing or liner: Length:
Diameter of Screen:
Type of Well: Drilled Gravel Pack Driven Other
Use of Well: For home For industry For public supply Stock
Method of Drilling: Cable Tools Rotary Rev. Rotary Det Driven Driven
Static water level in completed well (Distance from ground to water level)it.
Bailer Test: Hours tested Rateg.p.m. Drawdown f. (Difference between
Pumping Test: Hours tested 2 Rate 10 g.p.m. Drawdown 85ft. level at end of test)
Signature Tight 94 mlz

FOR WELL LOG SPACE USE REVERSE SIDE OF THIS SHEET

INSTRUCTIONS

This Water Well Record form is designed to record the most essential data concerning a water well. We request that you be as accurate as possible in recording this information as it may be of great assistance in the planning and development of new water supplies.

An accurate location of the well is equally as important as an accurate well log. Please include all information possible in the space provided for well location.

REMARKS:

As specified in Chapter 6 of the Acts of 1959, a copy of this report must be submitted within thirty days after the completion of a well to the Division of Water

DIVISION OF WATER RESOURCES
INDIANA DEPARTMENT OF CONSERVATION
609 STATE OFFICE BUILDING
INDIANAPOLIS, INDIANA 46209
MElrose 3-6757

STREMMEL & 1984.
Phone 981-4191
LaFontaine, Indiane

WATER WELL RECORD

Non-responsive, well locations
County in
Congressi
Describe
or disting
Name of owner: Non-responsive, pii
Name of Well Drilling Contractor: Strenmel # Hill
Address: 105 West Kendull Street LaFontaine, Indiana
Name of Drilling Equipment Operator: Cecil Siders
INFORMATION ON THE WELL
Completed depth of well: 72 ft. Date well was completed: September 17, 1964
Diameter of outside casing or drive pipe:Length:
Diameter of inside casing or liner: Length:
Diameter of Screen:Length:Slot size:
Type of Well: Drilled XX Gravel Pack Driven Other
Use of Well: For home For industry For public supply Stock
Method of Drilling: Cable Tools XX Rotary Rev. Rctary Det Driven Driven
Static water level in completed well (Distance from ground to water level) 20 ft
Bailer Test: Hours tested Rate 15 g.p.m. Drawdown none ft. (Difference between
Static level and water Pumping Test: Hours tested 3 Rate 20 g.p.m. Drawdown none ft. level at end of test)
Signature Stremmel/& H11
Date October 5, 1964

FOR WELL LOG SPACE USE REVERSE SIDE OF THIS SHEET

WATER WELL LOG			
FORMATIONS (Color, type of material, hardness, etc.)	From	То	Topo Map: Topo Map: Topo Map: Well log classified Courthouse located Field located Acc. w/o verificati
top soil and hard pan	0	g	viap:
blue clay	. 8	28	classified classified se located sated verification
dry gravel	28	30	A/O sifie cated ficat
hard dry white stone	30	49	H B B De T
medium soft blue stone	49	66	By L By L By L
soft blue water-bearing stone	66	72	
			Date Date Date Date
			1 [P] [S.] - 1 [PSK)
			20.0
			N E S E
			of I
		····	NT.
			Gro Dep Bed Aqu
			Ground e Depth to Bedrock (
			elev elev to be k ele r ele
			elevation o bedrock elevation elevation
REMARKS:			
			2,000
			C
		·	

INSTRUCTIONS

This Water Well Record form is designed to record the most essential data concerning a water well. We request that you be as accurate as possible in recording this information as it may be of great assistance in the planning and development of new water supplies.

An accurate location of the well is equally as important as an accurate well log. Please include all information possible in the space provided for well location.

As specified in Chapter 6 of the Acts of 1959, a copy of this report must be submitted within thirty days after the completion of a well to the Division of Water Resources Indiana

DIVISION OF WATER RESOURCES INDIANA DEPARTMENT OF CONSERVATION 311 WEST WASHINGTON STREET INDIANAPOLIS, INDIANA

WATER WELL RECORD

Non-responsive, well locations County in which well was d
Congressional township:
Describe in your own words the well location with respect to hearby towns, roads, streets
or distinctive landmarks:
Name of owner Non-responsive, PII
Name of Well Drilling Contractor: Jugal It safe
Address: R3 Watash Int.
Name of Drilling Equipment Operator:
INFORMATION ON THE WELL Completed depth of well: 19/ ft. Date well was completed: 3 -/4- 6/ Diameter of outside casing or drive pipe: 4// Length: 124/
Diameter of inside casing or liner: Length: Slot size:
Type of Well: Drilled Gravel Pack Driven Other
Use of Well: For home For industry For public supply Stock
Method of Drilling: Cable Tools Rotary Rev. Rotary Jet Driven
Static water level in completed well (Distance from ground to water level) 22 ft.
Bailer Test: Hours tested Rateg.p.m. Drawdown ft. (Difference between
Pumping Test: Hours tested 3 Rate 15 g.p.m. Drawdown 40 ft. level at end of test
Signature August August Date 3-15

FOR WELL LOG SPACE USE REVERSE SIDE OF THIS SHEET

WATER WELL LOG			·				
FORMATIONS (Color, type of material, hardness, etc.)	From	То	Well I	5 <u>C</u>	Topo. Map:	COUNTY:	
clay sont clay	0	45	Log p	င် ရွှေ	Map:	` 	
send	45	20	processed by:	7		ion-responsive	
clay	70	104	ased	surface			
sand \$20'	104	124	by:		3		
limestone	124	191		at well:	20		
				11:_	ebasi		
••			80		حدا		
			6	700	7	(Well	3
4			6				FOR A
						rill	DMIN
				ت ن ا	Į.	Driller'dges	ADMINISTRATIVE
			Placed	Courthouse Lo Field Located	Loc.	oes 1	ATIV
			d in	hous	accepted	not	E USE
			in Master	e Loc. ated	pted	fill	E ONLY
	8	98	ter		w/o	not fill out)	TX
		2	Well	Ву	ver		
			i .	3	ific		
			File		verification		रही हैं
			i	Date	n Yes		2 2 2
			te	те Те	S		325
REMARKS:				7. 2	- No -	C	35
				? (6			252
		· <u>····</u> ····					L'a
INSTRUCTIONS	5						ξ.

This Water Well Record form is designed to record the most essential data concerning a water well. We request that you be as accurate as possible in recording this information as it may be of great assistance in the planning and development of new water supplies.

An accurate location of the well is equally as important as an accurate well log. Please include all information possible in the space provided for well location.

As specified in Chapter 6 of the Acts of 1959, a copy of this report must be submitted within thirty days after the completion of a well to the Division of Water Resources, Indiana Department of Conservation, 311 West Washington Street, Indianapolis, Indiana.

DIVISION OF WATER RESOURCES
INDIANA DEPARTMENT OF CONSERVATION
609 STATE OFFICE BUILDING
INDIANAPOLIS 9, INDIANA

Waban

Non-responsive, well locations

INF
County in which well was drilled:_
Congressional township:
(Fill i Describe in your own words the wel
or distinctive landmarks: see
Davis Homes, Name of owner:Non-responsive, Pl
Name of Well Drilling Contractor: Midwestern Drilling Contractors.
Address: 7044 S. Main St. Anderson, Ind.
Name of Drilling Equipment Operator: Charles & Elwood Norris
INFORMATION ON THE WELL
Completed depth of well: 105 ft. Date well was completed: May 26, 1967
Diameter of outside casing or drive pipe: 4½ Length: 84
Diameter of inside casing or liner: 4" Length:
Diameter of Screen: none Length: Slot size:
Type of Well: Drilled 🗷 Gravel Pack 🗌 Driven 🗍 Other
Use of Well: For home 🗷 For industry 🗌 For public supply 🗋 Stock 🗍
Method of Drilling: Cable Tools C Rotary Rev. Rotary Jet C Driven C
Static water level in completed well (Distance from ground to water level) 15 ft.
Bailer Test: Hours testedRateg.p.m. Drawdownft. (Difference between
static level and water Pumping Test: Hours tested <u>l</u> Rate 150 g.p.Hn. Drawdown 60 ft. level at end continue to TRACTOR 2318 MONROE ST.
Signature <u>Malexim</u> Henrica. Ph.
Date May 29, 1967
FOR WELL LOG SPACE USE REVERSE SIDE OF THIS SHEET

This Water Well Record form is designed to record the most essential data concerning a water well. We request that you be as accurate as possible in recording this information as it may be of great assistance in the planning and development of new water supplies.

of NL of SL

An accurate location of the well is equally as important as an accurate well log. Please include all information possible in the space provided for well location.

REMARKS:

As specified in Chapter 6 of the Acts of 1959, a copy of this report must be submitted within thirty days after the completion of a well to the Division of Water Resources, Indiana. Department of Conservation.